



## CESCOM 20 - Projected Maintenance Due

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:39AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>0.22</b>	<b>0.23</b>	<b>25.97</b>	<b>21</b>	<b>114</b>	<b>3</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>0.22</b>	<b>0.23</b>	<b>25.97</b>	<b>21</b>	<b>114</b>	<b>3</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>0.22</b>	<b>0.23</b>	<b>25.97</b>	<b>21</b>	<b>114</b>	<b>3</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>0.90</b>	<b>0.9</b>	<b>102.6</b>		<b>114</b>	<b>3</b>

**\*\* Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

### Service Bulletins

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	DUE 1	Remains
Position	Drawing # / Task #	City Mod Lvl Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	DUE 2	Remains
SL 525-53-05 53SL-05	INTERCOSTAL DRAINAGE PATH INSPECTION		MTH HRS		300 HRS		2663	66.5
			RECOMMENDED					
SB 525-27-19 R1	ELEVATOR TRIM CABLE THICKNESS CHANGE AND VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION		MTH HRS		36 MTH 1200 HRS		13-Sep-2013 3650.78	21 m 5 d 1054.28
			MANDATORY					
SB FJ44-72-051 R3 E1	REWORK NAMEPLATE		HRS LDG MSC				2994.9 2819	398.4 729
			RECOMMENDED					
SB FJ44-72-051 R3 E2	REWORK NAMEPLATE		HRS LDG MSC				2994.9 2819	398.4 729
			RECOMMENDED					
SB FJ44-72-076 E1	REWORK - ENGINE- COMPRESSOR STATOR		HRS LDG MSC				2994.9 2819	398.4 729
			OPTIONAL					
SB FJ44-72-076 E2	REWORK - ENGINE- COMPRESSOR STATOR		HRS LDG MSC				2994.9 2819	398.4 729
			OPTIONAL					
SB FJ44-72-083 R4 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION		HRS LDG MSC				2994.9 2819	398.4 729
			OPTIONAL					
SB FJ44-72-083 R4 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION		HRS LDG MSC				2994.9 2819	398.4 729
			OPTIONAL					
SB FJ44-72-087 R4 E1	ENGINE - BLEED VALVE SHAFT - REPLACE		HRS LDG MSC				2994.9 2819	398.4 729
			OPTIONAL					
SB FJ44-72-087 R4 E2	ENGINE - BLEED VALVE SHAFT - REPLACE		HRS LDG MSC				2994.9 2819	398.4 729
			OPTIONAL					
SB FJ44-72-083 R3 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION		LDG MSC				2819	729
			OPTIONAL					
SB FJ44-72-083 R3 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION		LDG MSC				2819	729
			OPTIONAL					
SB FJ44-72-087 R3 E1	ENGINE - BLEED VALVE SHAFT - REPLACE		LDG MSC				2819	729
			OPTIONAL					
SB FJ44-72-087 R3 E2	ENGINE - BLEED VALVE SHAFT - REPLACE		LDG MSC				2819	729
			OPTIONAL					



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
052504	INSPECT LIFE VEST RECERTIFICATION	SLC			MTH 30-Jul-2010 HRS 2445.8 LDG 1949		60		01-Apr-2015	39 m 24 d
053412	INSPECT SKYWATCH HP INSPECTION				MTH 28-May-2010 HRS 2424.1 LDG 1930		36 1200		31-May-2013 3624.1	17 m 23 d 1027.6
053414	INSPECT TAWS 8000 TERR AWARE INSPECT				MTH 28-May-2010 HRS 2424.1 LDG 1930		36 1200		31-May-2013 3624.1	17 m 23 d 1027.6
5-12-01 0512001B	INSPECTION DOCUMENT 01	SLC			MTH 04-Dec-2009 HRS 2363		300		2663	66.5
5-12-02 0512002	INSPECTION DOCUMENT 02	SMF			MTH 07-Dec-2011 HRS 2596.5 LDG 2090		12		31-Dec-2012	12 m 23 d
B262201 COCKPIT 0512016	FUNCTIONAL (WEIGHT) CHECK PORTABLE FIRE EXTINGUISHER	SMF		A352GS V533271	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		12		31-Dec-2012	12 m 23 d
5-12-03 0512003	INSPECTION DOCUMENT 03	SLC			MTH 05-Nov-2010 HRS 2469.9 LDG 1977		24		30-Nov-2012	11 m 22 d
5-12-04	INSPECTION DOCUMENT 04				MTH 30-Jul-2010 HRS LDG		36			
A323101 0512004 : GEAR	RESTORATION (HYDROSTATIC TEST) EMERGENCY GEAR BOTTLE	SLC		9912368-2 4667	MTH 30-Jul-2010		36		31-Jul-2013	19 m 23 d
5-12-05	INSPECTION DOCUMENT 05				MTH 23-Mar-2009 HRS 2251 LDG		60			
B262002 LEFT 0512005 : L	RESTORATION (HYDROSTATIC TEST) FIRE EXTINGUISHER BOTTLE	SLC		30400031-1 41524B1	MTH 23-Mar-2009 HRS 2251		60		31-Mar-2014	27 m 23 d
B262002 RIGHT 0512005 : R	RESTORATION (HYDROSTATIC TEST) FIRE EXTINGUISHER BOTTLE	SLC		30400031-1 43139B1	MTH 23-Mar-2009 HRS 2251		60		31-Mar-2014	27 m 23 d
5-12-06	INSPECTION DOCUMENT 06	KSLC			MTH 22-Jul-2011		72			
A262201 COCKPIT 0512006	DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER	KSLC		A352GS V533271	MTH 22-Jul-2011		72		31-Jul-2017	67 m 23 d
5-12-07	INSPECTION DOCUMENT 07	KSLC			MTH 22-Jul-2011		144			
B262202 COCKPIT 0512007	RESTORATION (HYDROSTATIC TEST) PORTABLE FIRE EXTINGUISHER	KSLC		A352GS V533271	MTH 22-Jul-2011		144		31-Jul-2023	139 m 23 d
5-12-08 0512008	INSPECTION DOCUMENT 08	SLC			MTH 30-Jul-2010 HRS 2445.8 LDG 1949		24 300		31-Jul-2012 2745.8	7 m 23 d 149.3
5-12-10 0512010	INSPECTION DOCUMENT 10	SMF			MTH 07-Dec-2011 HRS 2596.5 LDG 2090		36 1200		31-Dec-2014 3796.5	36 m 23 d 1200
5-12-11 0512011	INSPECTION DOCUMENT 11	SMF			MTH 07-Dec-2011 HRS 2596.5 LDG 2090		36 1200		31-Dec-2014 3796.5	36 m 23 d 1200

PARTIALLY ACCOMPLISHED

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
5-12-12 <i>0512012</i>	INSPECTION DOCUMENT 12	SMF			MTH 07-Dec-2011 HRS 2596.5 LDG 2090		12		31-Dec-2012	12 m 23 d
5-12-13	INSPECTION DOCUMENT 13				MTH 28-May-2010 HRS 2424.1 LDG 1930		24			
341057 LEFT <i>0512013B : L-ADC</i>	CALIBRATION TEST ADC/ALT UNIT (91.411): INSPECTION DOCUMENT 13			70251N02D04 02090830D	MTH 28-May-2010 HRS 2424.1 LDG 1930		24		31-May-2012	5 m 23 d
341058 RIGHT <i>0512013B : R-ADC</i>	CALIBRATION TEST ADC/ALT UNIT (91.411): INSPECTION DOCUMENT 13			70251N02D04 02070758	MTH 28-May-2010 HRS 2424.1 LDG 1930		24		31-May-2012	5 m 23 d
341060 <i>0512013 : RVSM</i>	INSPECT RVSM SKIN WAVINESS CHECK: INSPECTION DOCUMENT 13				MTH 28-May-2010 HRS 2424.1 LDG 1930		24		31-May-2012	5 m 23 d
341106 STANDBY <i>0512013 : STDBY</i>	CALIBRATION TEST ENCODING ALTIMETER (FAR 91.411): INSPECTION DOCUMENT 13			44929-013 1732	MTH 28-May-2010 HRS 2424.1 LDG 1930		24		31-May-2012	5 m 23 d
B341011 LEFT <i>0512013 : L</i>	FUNCTIONAL CHECK PITOT-STATIC SYSTEMS: INSPECTION DOCUMENT 13				MTH 28-May-2010 HRS 2424.1 LDG 1930		24		31-May-2012	5 m 23 d
B341011 RIGHT <i>0512013 : R</i>	FUNCTIONAL CHECK PITOT-STATIC SYSTEMS: INSPECTION DOCUMENT 13				MTH 28-May-2010 HRS 2424.1 LDG 1930		24		31-May-2012	5 m 23 d
B345401 NO. 1 <i>0512013 : 1</i>	CALIBRATION CHECK TRANSPONDER ATC SYSTEM (FAR 91.413): INSPECTION DOCUMENT 13			066-01141-1101 13787	MTH 28-May-2010 HRS 2424.1 LDG 1930		24		31-May-2012	5 m 23 d
B345401 NO. 2 <i>0512013 : 2</i>	CALIBRATION CHECK TRANSPONDER ATC SYSTEM (FAR 91.413): INSPECTION DOCUMENT 13			066-01141-1101 11596	MTH 28-May-2010 HRS 2424.1 LDG 1930		24		31-May-2012	5 m 23 d
5-12-14	INSPECTION DOCUMENT 14				MTH 19-May-1999		A/R			
A324103 LEFT <i>0512014 : L</i>	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI): INSPECTION DOCUMENT 14	SMF		3-1527-2 05740737	MTH 07-Dec-2011 HRS 2596.5 LDG 2090			T/C		
A324103 NOSE <i>0512014 : NOSE</i>	SPECIAL DETAIL INSPECT LANDING GEAR WHEEL ASSY (NDI): INSPECTION DOCUMENT 14	SLC		3-1418 4809	MTH 24-Aug-2009 HRS 2314 LDG 1824			T/C		
A324103 RIGHT <i>0512014 : R</i>	SPECIAL DETAIL INSPECT MAIN LANDING GEAR WHEEL (NDI): INSPECTION DOCUMENT 14	SLC		3-1527-1 0992	MTH 29-Aug-2008 HRS 2150 LDG 1679			T/C		
5-12-17	INSPECTION DOCUMENT 17	SMF			MTH 07-Dec-2011 HRS 2596.5 LDG 2090		100			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
D243201 0512017A	FUNCTIONAL CHECK MAIN BATTERY NICKEL-CADMIUM BATTERY(CAPACITY CHECK): INSPECTION DOCUMENT 17	SMF		9914058-6 10602904	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		150		2746.5	150
5-12-18 0512018	INSPECTION DOCUMENT 18	SLC			MTH 31-Jan-2011 HRS 2513.3 LDG 2020		150		2663.3	66.8
5-12-21 0512021	INSPECTION DOCUMENT 21	SLC			MTH 05-Nov-2010 HRS 2469.9 LDG 1977		24 600		30-Nov-2012 3069.9	11 m 22 d 473.4
5-12-22	INSPECTION DOCUMENT 22	SMF			MTH 07-Dec-2011 HRS 2596.5 LDG 2090		300			
A361002 LEFT 0512022 : L	DETAILED INSPECTION B/A PRECOOLER ASSEMBLY : INSPECTION DOCUMENT 22	SMF		8161-1 S4883T0648	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		300		2896.5	300
A361002 RIGHT 0512022 : R	DETAILED INSPECTION B/A PRECOOLER ASSEMBLY : INSPECTION DOCUMENT 22	SMF		9914402-2 S4883T1794	MTH 07-Dec-2011 HRS 2596.5 LDG 2090	2596.5	1200		3796.5	1200
5-12-29	INSPECTION DOCUMENT 29				MTH 19-May-1999 HRS 0		7200		7200	4603.5
5-12-33 0512033	INSPECTION DOCUMENT 33	SLC			MTH 23-Apr-2011 HRS 2557.1 LDG 2054		12 300		30-Apr-2012 2857.1	4 m 22 d 260.6
5-12-34 0512034	INSPECTION DOCUMENT 34	SLC			MTH 26-Aug-2011 HRS 2572.8 LDG 2071 ACH 765.2		800		1565.2	800
5-12-35 0512035	INSPECTION DOCUMENT 35	*CF			MTH 19-May-1999 ACH 0		1500		1500	734.8
5-12-MA 05120MA	INSPECTION DOCUMENT MA	SLC			MTH 23-Apr-2011 HRS 2557.1 LDG 2054		300		2857.1	260.6
5-12-MC 05120MC	INSPECTION DOCUMENT MC	SLC			MTH 01-Dec-2009 HRS 2363		1200		3563	966.5
5-12-MD 05120MD	INSPECTION DOCUMENT MD	*CF			MTH 19-May-1999 LDG 0		5000		5000	2910
5-12-MF 05120MF	INSPECTION DOCUMENT MF	*CF			MTH 19-May-1999 HRS 0		6000		6000	3403.5
5-12-MG 05120MG	INSPECTION DOCUMENT MG	*CF			MTH 19-May-1999 HRS 0		6000		6000	3403.5
5-12-MH 05120MH	INSPECTION DOCUMENT MH	*CF			MTH 19-May-1999 HRS 0		6000		6000	3403.5
5-12-MI 05120MI	INSPECTION DOCUMENT MI	*CF			MTH 19-May-1999 HRS 0		7200		7200	4603.5
5-12-MJ 05120MJ	INSPECTION DOCUMENT MJ	*CF			MTH 19-May-1999 HRS 0		7200		7200	4603.5
5-12-MK 05120MK	INSPECTION DOCUMENT MK	*CF			MTH 19-May-1999 HRS 0		7900		7900	5303.5
5-12-ML 05120ML	INSPECTION DOCUMENT ML	*CF			MTH 19-May-1999 HRS 0		9600		9600	7003.5
5-12-MO 05120MO	INSPECTION DOCUMENT MO	*CF			MTH 19-May-1999 HRS 0		15200		15200	12603.5

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
051201 E1 <i>051200A : E1**L</i>	FJ44 CHECK 1	SLC			MTH 31-Jan-2011 HRS 2513.3 LDG 2020		150		2663.3	66.8
051201 E2 <i>051200A : E2**R</i>	FJ44 CHECK 1	SLC			MTH 31-Jan-2011 HRS 2513.3 LDG 2020		150		2663.3	66.8
051202 E1 <i>051204 : E1**L</i>	FJ44 CHECK 2	SLC			MTH 09-Mar-2010 HRS 2381.1 LDG 1894	-17.8	300		2663.3	66.8
051202 E2 <i>051204 : E2**R</i>	FJ44 CHECK 2	SLC			MTH 09-Mar-2010 HRS 2381.1 LDG 1894	-17.8	300		2663.3	66.8
051203 E1	FJ44 CHECK 3				MTH 21-Nov-2005 HRS 1494.9 LDG 1069	.1	4500 5250		5995 6319	3398.5 4229
051203 E2	FJ44 CHECK 3				MTH 21-Nov-2005 HRS 1494.9 LDG 1069	.1	4500 5250		5995 6319	3398.5 4229
051204 E1 <i>051204B : E1**L</i>	FJ44 CHECK 4	SLC			MTH 19-May-1999 HRS 0 LDG 0	-1505.1 -2431	4500 5250		2994.9 2819	398.4 729
051204 E2 <i>051204B : E2**R</i>	FJ44 CHECK 4	SLC			MTH 19-May-1999 HRS 0 LDG 0	-1505.1 -2431	4500 5250		2994.9 2819	398.4 729
051205 E1	FJ44 CHECK 5				MTH 19-May-1999 HRS 0 LDG 0	-5 -681	4500 5250		4495 4569	1898.5 2479
051205 E2	FJ44 CHECK 5				MTH 19-May-1999 HRS 0 LDG 0	-5 -681	4500 5250		4495 4569	1898.5 2479
350002 <i>0512004 : OXY</i>	RESTORATION (HYDROSTATIC TEST) OXYGEN BOTTLE	SLC		176274-50 6280	MTH 23-Mar-2009 HRS 2251		60		31-Mar-2014	27 m 23 d
551010 <i>045503</i>	EXAMINE HORIZONTAL STABILIZER FRONT UPPER SPAR CAP AT SS 4.78		*CF		MTH 19-May-1999 HRS 0		14000		14000	11403.5
571010 <i>045701</i>	EXAMINE LOWER MAIN SPAR SPLICE AT WS 93.00		*CF		MTH 19-May-1999 HRS 0		13200		13200	10603.5
571015 <i>045702</i>	EXAMINE LOWER REAR SPAR SPLICE AT WS 93.00		*CF		MTH 19-May-1999 HRS 0		15000		15000	12403.5
571020 <i>045703</i>	EXAMINE MAIN SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0)		*CF		MTH 19-May-1999 HRS 0		15000		15000	12403.5
571025 <i>045704</i>	EXAMINE REAR SPAR CARRY-THROUGH LOWER CAP (RWS 42.0 TO LWS 42.0)		*CF		MTH 19-May-1999 HRS 0		15000		15000	12403.5
571030 <i>045705</i>	EXAMINE MAIN SPAR OUTBOARD LOWER CAP (WS 120.0 TO WS 152.00)		*CF		MTH 19-May-1999 HRS 0		15000		15000	12403.5



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
211002	B/A FLOW CONTROL VALVE 9912420-3	*CF		1H124-8 1AR8	MTH 19-May-1999		O/C			
211003	HEAT PRESSURE EXCHANGER	*CF		10840A 435	MTH 19-May-1999		O/C			
211004	HEAT EXCHANGER SHUTOFF VALVE	*CF		27241287-15 10AP51	MTH 19-May-1999		O/C			
211005	EMERGENCY PRESS SHUTOFF VALVE 9912422-1	*CF		2601-7 347	MTH 19-May-1999		O/C			
212001	UNDERFLOOR INLET AIR BLOWER	*CF		0113-12 368	MTH 19-May-1999		O/C			
212003	TEMP PRESS COMPRESSION SWITCH	*CF		1173T42-3 2571	MTH 19-May-1999		O/C			
212011 AFT	TEMP UNDERFLOOR SENSOR 9912085-3	*CF		27221274 1AR1	MTH 19-May-1999		O/C			
212202	OVERHEAD AIR VALVE SOLENOID	*CF		D113204 SN-UNKNOWN	MTH 19-May-1999		O/C			
212203	ACTUATOR	*CF		D-68070-A-1 SN-UNKNOWN	MTH 19-May-1999		O/C			
212302	BLOWER - WINDSHIELD AIR MOTOR	*CF		7003-200 508	MTH 19-May-1999		O/C			
212401	AVIONICS COOLING BLOWER	*CF		071-04037-0003 SN-UNKNOWN	MTH 19-May-1999		O/C			
212403	AVIONICS COOLING BLOWER	*CF		19A827 SN-UNKNOWN	MTH 19-May-1999		O/C			
212404 NOSE	AVIONICS COOLING FAN	*CF		032105 SN-UNKNOWN	MTH 19-May-1999		O/C			
213001	PRESS MASTER OUTFLOW VALVE 9912409-2	*CF		52771-101 622	MTH 19-May-1999		O/C			
213002	PRESS SECONDARY OUTFLOW VALVE 9912409-3	*CF		52772-101 693	MTH 19-May-1999		O/C			
213003	PRESSURIZATION CONTROLLER 9912409-6	SLC		52770-112 K211	MTH 05-Mar-2006 HRS 1578		O/C	0		
213005	DIFFERENTIAL PRESS INDICATOR	*CF		C668511-0105 21014	MTH 19-May-1999		O/C			
213008	PRESS MANUAL CONTROL SWITCH 9912409-4	*CF		52773-001 690	MTH 19-May-1999		O/C			
215001	FORWARD EVAPORATOR	*CF		1134820-1 308	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
215002	AFT EVAPORATOR	*CF		1134820-2 340	MTH 19-May-1999		O/C			
215003 AFT	EVAPORATOR MOTOR	*CF		1250210-1 SN-UNKNOWN	MTH 19-May-1999		O/C			
215003 FORWARD	EVAPORATOR MOTOR	*CF		1250210-1 SN-UNKNOWN	MTH 19-May-1999		O/C			
215004	AIR CONDITIONER COMPRESSOR	SLC		1134160 6095	MTH 26-Aug-2011 HRS 2572.8 LDG 2071 ACH 765.2		O/C	0 0 0 0		
215005	AIR CONDITIONER CONDENSER	*CF		1134180-1 383	MTH 19-May-1999		O/C			
215006	COMPRESSOR DRIVE MOTOR	*CF		1134103-1 1201	MTH 19-May-1999 ACH 0	13	3000	13	3000	2234.8
215007	RECEIVER DRYER ASSEMBLY	*CF		1134140-3 SN-UNKNOWN	MTH 19-May-1999		O/C			
215008	BINARY SWITCH	SWF		1250232-7 695	MTH 07-Sep-2001 ACH 210		O/C	0		
215009	A/C FLIGHT HOUR METER	*CF		1250703-3 SN-UNKNOWN	MTH 19-May-1999		O/C			
215011	AIR CONDITIONER DRIVE BELT R134A	SLC		232L100 N/A	MTH 26-Aug-2011 HRS 2572.8 LDG 2071 ACH 765.2		O/C	0 0 0 0		
215012	COMPRESSOR MOTOR BRUSHES	SLC		1251171-6 NSN	MTH 26-Aug-2011 HRS 2572.8 LDG 2071 ACH 765.2		800	565.2	1000	234.8
215013 AFT	EXPANSION VALVE	*CF		1250218 SN-UNKNOWN	MTH 19-May-1999		O/C			
215013 FORWARD	EXPANSION VALVE	*CF		1250218 SN-UNKNOWN	MTH 19-May-1999		O/C			
216002	TEMPERATURE CONTROLLER	*CF		1E58-6 10AP70	MTH 19-May-1999		O/C			
216003	TEMP CNTL SYS SENSOR 9912085-3	*CF		27221274 2AR84	MTH 19-May-1999		O/C			
221002	AUTOPILOT COMPUTER CONTROL PC-400	ABQ		7003897-923 02032655	MTH 26-Jun-2006 HRS 1650		O/C	1812		
221003 AILERON	SERVO SM-200	*CF		4006719-906 98111502	MTH 19-May-1999		O/C			
221004 RUDDER	SERVO SM-200	*CF		4006719-906 98111469	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
221005 ELEVATOR	SERVO SM-200	*CF		4006719-914 99021822	MTH 19-May-1999		O/C			
232001 NO. 1	COMM RADIO SYSTEM CONTROL KY-196A	ICT	9	064-01054-0050 26041	MTH 12-May-2000 HRS 279		O/C	279		
232001 NO. 2	COMM RADIO SYSTEM CONTROL KY-196A	ICT	9	064-01054-0050 25760	MTH 12-May-2000 HRS 279		O/C	279		
232008 BOTTOM	COMM 1 ANTENNA	*CF		17-40-02W 424	MTH 19-May-1999		O/C			
232008 TOP	COMM 2 ANTENNA	*CF		18-50-01 96	MTH 19-May-1999		O/C			
232010	SATELITE DATA LINK TRANSCEIVER AV-200	SLC		305391-000 1148	MTH 22-Jul-2004 HRS 1058		O/C	0		
235001 LEFT	AUDIO AMPLIFIER S3100-62	TOL		5635-1-1 668	MTH 20-Jun-2007 HRS 1863		O/C	0		
235001 RIGHT	AUDIO AMPLIFIER S3100-62	TOL		5635-1-1 710	MTH 20-Jun-2007 HRS 1863		O/C	1863		
237004	CVR IMPACT SWITCH	*CF		6895D2-5-5 SN-UNKNOWN	MTH 19-May-1999		O/C			
242001 NO. 1	SECOND AC POWER INVERTER S3100-39	*CF		PC251-123E 10122	MTH 19-May-1999		O/C			
242001 NO. 2	SECOND AC POWER INVERTER S3100-39		D	PC251-123E 8419	MTH 06-Oct-2006 HRS 1721		O/C	0		
243002 LEFT	GENERATOR CONTROL UNIT	*CF		51525-001F 99004	MTH 19-May-1999		O/C			
243002 RIGHT	GENERATOR CONTROL UNIT	*CF		51525-001F 98541	MTH 19-May-1999		O/C			
243003	MAIN BATTERY	SLC		9914058-6 10602904	MTH 31-Jan-2011 HRS 2513.3 LDG 2020		O/C			
243004	BATTERY TEMPERATURE MONITOR	*CF		1529-1-1 2926	MTH 19-May-1999		O/C			
243005	OVERVOLTAGE MONITOR	*CF		1645-1-3 1973	MTH 19-May-1999		O/C			
243006 LEFT	AMMETER	*CF		C662501-0105 K98109	MTH 19-May-1999		O/C			
243006 RIGHT	AMMETER	*CF		C662501-0105 K98110	MTH 19-May-1999		O/C			
243008	BATTERY DISCONNECT RELAY	*CF		A931F 38619	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
243011	VOLTMETER	*CF		C662502-0101 A99307	MTH 19-May-1999		O/C			
245001 LEFT	START PCB ASSY	*CF		6318324-2 SN-UNKNOWN	MTH 19-May-1999		O/C			
245001 RIGHT	START PCB ASSY	*CF		6318324-2 SN-UNKNOWN	MTH 19-May-1999		O/C			
245002 LEFT	ASSEMBLY-FUEL CONTROL PCB	*CF		6318321-3 SN-UNKNOWN	MTH 19-May-1999		O/C			
245002 RIGHT	ASSEMBLY-FUEL CONTROL PCB	*CF		6318321-3 SN-UNKNOWN	MTH 19-May-1999		O/C			
245003 LEFT	ASSEMBLY-IGNITOR PCB	*CF		6318322-1 SN-UNKNOWN	MTH 19-May-1999		O/C			
245003 RIGHT	ASSEMBLY-IGNITOR PCB	ICT		6318322-1 SN-UNKNOWN	MTH 27-Nov-2001 HRS 620		O/C	0		
245004 LEFT	ANTI ICE PCB ASSY	*CF		6318323-3 SN-UNKNOWN	MTH 19-May-1999		O/C			
245004 RIGHT	ANTI ICE PCB ASSY	*CF		6318323-3 SN-UNKNOWN	MTH 19-May-1999		O/C			
245005	ATTENUATOR PCB ASSY	*CF		6318355-2 SN-UNKNOWN	MTH 19-May-1999		O/C			
245006	ENVIRONMENTAL PCB ASSY	*CF		6318356-2 SN-UNKNOWN	MTH 19-May-1999		O/C			
245007	MISCELLANEOUS PCB ASSY	*CF		6318357-2 SN-UNKNOWN	MTH 19-May-1999		O/C			
245008	TRIM CONTROL PCB ASSY	SLC		6518351-10 0549	MTH 26-Mar-2004 HRS 944		O/C	0		
245009	DIMMING PCB ASSY	*CF		6518353-4 SN-UNKNOWN	MTH 19-May-1999		O/C			
245010	GEAR LOGIC PCB ASSY	*CF		6518354-3 SN-UNKNOWN	MTH 19-May-1999		O/C			
245011	FUEL FLOW XMITTER PCB ASSY 9912417-2	*CF		85-230-1 SN-UNKNOWN	MTH 19-May-1999		O/C			
256001	ELT TRANSMITTER ELT-110-4 ARTEX	*CF		453-0150 61100	MTH 19-May-1999		O/C			
256004	ELT ANTENNA	*CF		DMQ18-3 8331	MTH 19-May-1999		O/C			



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
256005	ELT BEACON BATTERY PACK	SMF		452-0130 11012013	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		24	0 0	31-Oct-2013	22 m 23 d
Manufacture Date: 15-Oct-2011										
256006 NO. 1	LIFE VEST	SLC		P01074-103 10040180024	MTH 30-Jul-2010 HRS 2445.8 LDG 1949		60	3 0 0	01-Apr-2015	39 m 24 d
256006 NO. 2	LIFE VEST	SLC		P01074-103 10040180019	MTH 30-Jul-2010 HRS 2445.8 LDG 1949		60	3 0 0	01-Apr-2015	39 m 24 d
256006 NO. 3	LIFE VEST	SMF		P01074-103 11070300031	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		60	4 0 0	31-Aug-2016	56 m 23 d
256006 NO. 4	LIFE VEST	SLC		P01074-103 10040180022	MTH 30-Jul-2010 HRS 2445.8 LDG 1949		60	3 0 0	01-Apr-2015	39 m 24 d
256006 NO. 5	LIFE VEST	SLC		P01074-103 10040180023	MTH 30-Jul-2010 HRS 2445.8 LDG 1949		60	3 0 0	01-Apr-2015	39 m 24 d
256006 NO. 6	LIFE VEST	SLC		P01074-103 10040180017	MTH 30-Jul-2010 HRS 2445.8 LDG 1949		60	3 0 0	01-Apr-2015	39 m 24 d
256006 NO. 7	LIFE VEST	SLC		P01074-103 10040180020	MTH 30-Jul-2010 HRS 2445.8 LDG 1949		60	3 0 0	01-Apr-2015	39 m 24 d
256055	FIRST AID KIT	SMF		932-1528-61 02012013	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		O/C	0 0 0	01-Feb-2013	13 m 24 d
261002 LEFT	FIRE DETECT SENSOR 9912416-1	*CF		30012121004/4559 202694	MTH 19-May-1999		O/C			
261002 RIGHT	FIRE DETECT SENSOR 9912416-1	*CF		30012121004/4559 202706	MTH 19-May-1999		O/C			
262001 LEFT	FIRE EXTINGUISHER BOTTLE 9912048-4	SLC		30400031-1 41524B1	MTH 23-Mar-2009 HRS 2251		O/C	0		
262001 RIGHT	FIRE EXTINGUISHER BOTTLE 9912048-4	SLC		30400031-1 43139B1	MTH 23-Mar-2009 HRS 2251		O/C	0		
262002 LEFT NO. 1	FIRE EXTINGUISHER CARTRIDGE SLC			13083-5 ESD08K325001	MTH 23-Mar-2009 HRS 2251		72	5	31-Oct-2014	34 m 23 d
262002 LEFT NO. 2	FIRE EXTINGUISHER CARTRIDGE SLC			13083-5 ESD08K325001	MTH 23-Mar-2009 HRS 2251		72	5	31-Oct-2014	34 m 23 d
262002 RIGHT NO. 1	FIRE EXTINGUISHER CARTRIDGE SLC			13083-5 ESD08K325001	MTH 23-Mar-2009 HRS 2251		72	5	31-Oct-2014	34 m 23 d
262002 RIGHT NO. 2	FIRE EXTINGUISHER CARTRIDGE SLC			13083-5 ESD08K325001	MTH 23-Mar-2009 HRS 2251		72	5	31-Oct-2014	34 m 23 d
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER HALON 1211	SWF		A352GS V533271	MTH 24-Dec-1999 HRS 157		O/C	7		



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
273001 LEFT	SHAKER CONTROL	*CF		201 4190	MTH 19-May-1999		O/C			
273002	ELEVATOR ELECTRIC TRIM SERVO	*CF		44430-3548 T377	MTH 19-May-1999		O/C			
273003	SERVO MOUNT ASSY	*CF		44575-3415 SN-UNKNOWN	MTH 19-May-1999		O/C			
273004 LEFT	ELEVATOR TRIM ACTUATOR	*CF		6361215-21 SN-UNKNOWN	MTH 19-May-1999		O/C			
273004 RIGHT	ELEVATOR TRIM ACTUATOR	*CF		6361215-22 SN-UNKNOWN	MTH 19-May-1999		O/C			
273005	RUDDER TRIM ACTUATOR	GJT		6361215-21 06254	MTH 26-Nov-2008 HRS 2199		O/C	0		
275001	SHUTOFF VALVE	*CF		4083 337	MTH 19-May-1999		O/C			
275002 LEFT	FLAP HYD ACTUATOR 9912365-4	*CF		1542000-3 660	MTH 19-May-1999		O/C			
275002 RIGHT	FLAP HYD ACTUATOR 9912365-4	*CF		1542000-3 668	MTH 19-May-1999		O/C			
276001 LEFT	SPEEDBRAKE ACTUATOR 9912375-3	*CF		1542100-3 677	MTH 19-May-1999		O/C			
276001 RIGHT	SPEEDBRAKE ACTUATOR 9912375-3	*CF		1542100-3 680	MTH 19-May-1999		O/C			
281001 LEFT	FUEL SURGE VALVE 9912016-2	*CF		35C10D 1163	MTH 19-May-1999		O/C			
281001 RIGHT	FUEL SURGE VALVE 9912016-2	*CF		35C10D 1186	MTH 19-May-1999		O/C			
282001 LEFT	ELECTRIC FUEL PUMP 9912017-4	*CF		1C7-13 8AP74	MTH 19-May-1999		O/C			
282001 RIGHT	ELECTRIC FUEL PUMP 9912017-4	*CF		1C7-13 7AP67	MTH 19-May-1999		O/C			
282002 LEFT	FUEL TRANSFER PUMP 9912190-3	*CF		RG45880 B691	MTH 19-May-1999		O/C			
282002 RIGHT	FUEL TRANSFER PUMP 9912190-3	*CF		RG45880 B699	MTH 19-May-1999		O/C			
282004 LEFT	FUEL MOTOR ACTUATED VALVE 9912014-3	*CF		EM9014-3 619	MTH 19-May-1999		O/C			
282004 RIGHT	FUEL MOTOR ACTUATED VALVE 9912014-3	*CF		EM9014-3 598	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
282005 LEFT	FUEL TRANSFER EJECTOR 9912190-2	*CF		RG45310 B7559	MTH 19-May-1999		O/C			
282005 RIGHT	FUEL TRANSFER EJECTOR 9912190-2	*CF		RG45310 B7560	MTH 19-May-1999		O/C			
282006	TRANSFER VALVE 9914103-6	*CF		ZSV57 8121448	MTH 19-May-1999		O/C			
284001 LEFT	#5 FUEL TRANSMITTER 9912412-5	*CF		10307T01Y00 B753	MTH 19-May-1999		O/C			
284001 RIGHT	#5 FUEL TRANSMITTER 9912412-5	*CF		10307T01Y00 B780	MTH 19-May-1999		O/C			
284002 LEFT	FUEL QUANTITY TRANSMITTER 9912412-8	GJT		10309T03Y00 B599	MTH 26-Nov-2008 HRS 2199		O/C	0		
284002 RIGHT	FUEL QUANTITY TRANSMITTER 9912412-8	GJT		10309T03Y00 B1158	MTH 26-Nov-2008 HRS 2199		O/C	67		
284003	FUEL QUANTITY SIGNAL CONDITIONER 9912412-7	*CF		10310B01Y02 B437	MTH 19-May-1999		O/C			
284004 LEFT	#3 FUEL TRANSMITTER 9912412-3	*CF		10305T01Y00 B773	MTH 19-May-1999		O/C			
284004 RIGHT	#3 FUEL TRANSMITTER 9912412-3	*CF		10305T01Y00 B838	MTH 19-May-1999		O/C			
284005 LEFT	#4 FUEL TRANSMITTER 9912412-4	*CF		10306T01Y00 B770	MTH 19-May-1999		O/C			
284005 RIGHT	#4 FUEL TRANSMITTER 9912412-4	*CF		10306T01Y00 B812	MTH 19-May-1999		O/C			
284006 LEFT	#2 FUEL TRANSMITTER 9912412-2	*CF		10304T01Y00 B810	MTH 19-May-1999		O/C			
284006 RIGHT	#2 FUEL TRANSMITTER 9912412-2	*CF		10304T01Y00 B808	MTH 19-May-1999		O/C			
284007 LEFT	#1 FUEL TRANSMITTER 9912412-1	*CF		10303T01Y00 B802	MTH 19-May-1999		O/C			
284007 RIGHT	#1 FUEL TRANSMITTER 9912412-1	*CF		10303T01Y00 B790	MTH 19-May-1999		O/C			
284008 LEFT	FUEL LOW LEVEL SWITCH 9912412-2	*CF		GIF5400-40 SN-UNKNOWN	MTH 19-May-1999		O/C			
284008 RIGHT	FUEL LOW LEVEL SWITCH 9912412-2	*CF		GIF5400-40 SN-UNKNOWN	MTH 19-May-1999		O/C			
284009	FUEL QUANTITY/FUEL FLOW INDICATOR 9912399-10	MCO		10274N03M00 B583	MTH 14-Nov-2003 HRS 760		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
291002 LEFT	HYDRAULIC PUMP ASSY 9912392-2	SWF		4120-021003 31	MTH 24-Dec-1999 HRS 157		O/C	106		
291002 RIGHT	HYDRAULIC PUMP ASSY 9912392-2	SLC		4120-021003 597	MTH 29-Nov-2005 HRS 1500		O/C	0		
291003	HYDRAULIC CHECK VALVE *CF			CV02-193 SN-UNKNOWN	MTH 19-May-1999		O/C			
291005	HYDRAULIC RESERVOIR ASSEMBLY *CF			6317001-52 SN-UNKNOWN	MTH 19-May-1999		O/C			
291007	PRESSURE SWITCH 9912373-4	SLC		GPP1250-58 0539694	MTH 12-Dec-2005 HRS 1508		O/C	0		
291008	HYDRAULIC MANIFOLD ASSEMBLY 9912423-24	*CF		8184-8 339	MTH 19-May-1999		O/C			
291009	HYDRAULIC RELIEF VALVE *CF			1785-1 339	MTH 19-May-1999		O/C			
291010 LEFT	HYDRAULIC SHUTOFF VALVE ASSY 9912400-3	*CF		AV24B1388-1 T44142	MTH 19-May-1999		O/C			
291010 RIGHT	HYDRAULIC SHUTOFF VALVE ASSY 9912400-3	*CF		AV24B1388-1 T44140	MTH 19-May-1999		O/C			
291011 LEFT	FLOW SWITCH/CHECK HYD VALVE 9912393-2	SLC		MC19232-2 0748	MTH 23-Mar-2009 HRS 2251		O/C	0		
291011 RIGHT	FLOW SWITCH/CHECK HYD VALVE 9912393-2	*CF		MC19232-2 676	MTH 19-May-1999		O/C			
291011	SYSTEM RELIEF VALVE 9912423-12	SMF		2576 123C	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		O/C	2446.5		
291012	SPEED BRAKE DUMP VALVE SOLENOID 9912423-7	*CF		4082-2 3434	MTH 19-May-1999		O/C			
291013	LOADING VALVE SOLENOID 9912423-39	SLC		4134-4 744	MTH 08-Dec-2005 HRS 1506		O/C	0		
291014	GEAR VALVE SOLENOID 9912423-25	*CF		4051-1 346	MTH 19-May-1999		O/C			
291015	GEAR PORTION CHECK VALVE 9912423-13	*CF		9504 342	MTH 19-May-1999		O/C			
291016 LEFT	SPEED BRAKE PORTION VALVE 9912423-14	*CF		9505 696	MTH 19-May-1999		O/C			
291016 RIGHT	SPEED BRAKE PORTION VALVE 9912423-14	*CF		9505 695	MTH 19-May-1999		O/C			
291017	SPEED BRAKE PORTION VALVE 9912423-15	*CF		2577 344	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
291018	PNEUMATIC DUMP VALVE 9912423-17	*CF		9503-1 353	MTH 19-May-1999		O/C			
291019 LEFT	ATTENUATOR VALVE SOLENOID 9912423-19	*CF		4107-1 339	MTH 19-May-1999		O/C			
291019 RIGHT	ATTENUATOR VALVE SOLENOID 9912423-20	*CF		4107-2 341	MTH 19-May-1999		O/C			
291020 NO. 1	SPEEDBRAKE VALVE SOLENOID 9912423-6	*CF		4052-1 343	MTH 19-May-1999		O/C			
291021 NO. 1	FLAP VALVE SOLENOID 9912423-8	*CF		4052-2 349	MTH 19-May-1999		O/C			
291022	ELECTRO/HYDRAULIC SERVO VALVE *CF			37-509 335	MTH 19-May-1999		O/C			
301001	SHUTOFF ISOLATION VALVE 9912403-2	*CF		2602-36 138	MTH 19-May-1999		O/C			
301002 LEFT	PNEUMATIC DEICE SWITCH *CF			1106P55-1 727	MTH 19-May-1999		O/C			
301002 RIGHT	PNEUMATIC DEICE SWITCH *CF			1106P55-1 734	MTH 19-May-1999		O/C			
301003 LEFT	SHUTOFF PRESS REGULATOR VALVE 9912402-9	*CF		1H127-4 11AP184	MTH 19-May-1999		O/C			
301003 RIGHT	SHUTOFF PRESS REGULATOR VALVE 9912402-9	*CF		1H127-4 1AR17	MTH 19-May-1999		O/C			
301004 LEFT	TEMPERATURE DEICE SWITCH *CF			1173T42-4 722	MTH 19-May-1999		O/C			
301004 RIGHT	TEMPERATURE DEICE SWITCH *CF			1173T42-4 672	MTH 19-May-1999		O/C			
301010 LEFT	HORIZONTAL STABILIZER BOOT SLC			29S4D5244-11 SN-UNKNOWN	MTH 02-Jun-2005 HRS 1370		O/C	0		
301010 RIGHT	HORIZONTAL STABILIZER BOOT SLC			25S4D5244-02 1016	MTH 17-Mar-2009 HRS 2251		O/C	0		
301011	DEICE TAIL TIMER 9912440-1	*CF		937-1-1 380	MTH 19-May-1999		O/C			
302001 LEFT	SOLENOID VALVE 9912402-10	*CF		1H127-5 11AP126	MTH 19-May-1999		O/C			
302001 RIGHT	SOLENOID VALVE 9912402-10	*CF		1H127-5 1AR17	MTH 19-May-1999		O/C			
303002 LEFT	HEATED PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
303002 RIGHT	HEATED PITOT TUBE	*CF		PH502 SN-UNKNOWN	MTH 19-May-1999		O/C			
304001	B/A TEMP MONITOR	*CF		1169-1 2746	MTH 19-May-1999		O/C			
304002	HEAT EXCHANGER 9912041-3	*CF		10653A 1055	MTH 19-May-1999		O/C			
304003	WINDSHIELD S/O VALVE 9912402-9	*CF		1H127-4 1AR18	MTH 19-May-1999		O/C			
304004 LEFT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 3844	MTH 19-May-1999		O/C			
304004 RIGHT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 3843	MTH 19-May-1999		O/C			
304006	TEMP BLEED AIR CONTROLLER 9912085-6	*CF		1E58-1 8AP93	MTH 19-May-1999		O/C			
304007	TEMP CONTROL BLEED AIR VALVE 9912085-1	*CF		27241287 2AR21	MTH 19-May-1999		O/C			
304009 LEFT	SOLENOID DEICE VALVE	*CF		3D2353-06 N14664	MTH 19-May-1999		O/C			
304009 RIGHT	SOLENOID DEICE VALVE	*CF		3D2353-06 N15203	MTH 19-May-1999		O/C			
304010	ALCOHOL PUMP ASSEMBLY	*CF		476411 SN-UNKNOWN	MTH 19-May-1999		O/C			
304011	TEMPERATURE SENSOR 9912085-3	*CF		27221274 2AR83	MTH 19-May-1999		O/C			
304012 LEFT	WINDSHIELD BLEED AIR VALVE	*CF		1403-20 1340	MTH 19-May-1999		O/C			
304012 RIGHT	WINDSHIELD BLEED AIR VALVE	*CF		1403-20 1386	MTH 19-May-1999		O/C			
304013	PRESSURE WINDSHIELD SWITCH	*CF		1115P25 2883A	MTH 19-May-1999		O/C			
304014 AFT	TEMPERATURE EVAPORATOR SENSOR 9912085-3	*CF		27221274 1AR35	MTH 19-May-1999		O/C			
312001 LEFT	DIGITAL CLOCK	*CF		M877A5V 9654	MTH 19-May-1999		O/C			
313001	FLIGHT HOUR METER 85071	*CF		C664503-0104 SN-UNKNOWN	MTH 19-May-1999		O/C			
315001	CABIN ALTITUDE PRESSURE SWITCH 9910095-6	*CF		GB300NA161 9844707	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
315002	MASTER WARN ANNUNCIATOR ASSY SLC			9912438-9 438000139	MTH 21-Nov-2005 HRS 1494		O/C	0		
321001	AND ATTACHING HARDWARE ASSEMBLY LEFT MAIN LANDING GEAR		*CF	6341003-7 158	MTH 19-May-1999		O/C			
321001	STRUT AND ATTACHING HARDWARE ASSEMBLY NOSE LANDING GEAR		*CF	6342000-21 SN-UNKNOWN	MTH 19-May-1999 LDG 0		22500	0	22500	20410
321001	AND ATTACHING HARDWARE ASSEMBLY RIGHT MAIN LANDING GEAR		*CF	6341003-8 158	MTH 19-May-1999		O/C			
<i>321002 : R</i>										
321003	TRUNNION ASSEMBLY LEFT MAIN GEAR		*CF	6341007-3 SN-UNKNOWN	MTH 19-May-1999 LDG 0		12480	0	12480	10390
321004	TRUNNION ASSEMBLY RIGHT MAIN GEAR		*CF	6341007-4 SN-UNKNOWN	MTH 19-May-1999 LDG 0		12480	0	12480	10390
321005	TRAILING LINK AND AXLE ASSEMBLY LEFT		*CF	6341002-7 SN-UNKNOWN	MTH 19-May-1999 LDG 0		28300	0	28300	26210
321006	TRAILING LINK AND AXLE ASSEMBLY RIGHT		*CF	6341002-8 SN-UNKNOWN	MTH 19-May-1999 LDG 0		28300	0	28300	26210
321007	SHIMMY DAMPER ASSEMBLY *CF			6343001-5 3095	MTH 19-May-1999		O/C			
321008	OLEO ASSEMBLY LEFT	SLC		6341130-3 0352	MTH 31-Jan-2011 HRS 2513.3 LDG 2020		28300	2005	28315	26225
321008	OLEO ASSEMBLY RIGHT	SLC		6341130-3 337	MTH 05-Apr-2006 HRS 1601 LDG 1185		28300	1013	28472	26382
321009 <i>321004</i>	FORK AND PISTON ASSEMBLY *CF			6342000-3 SN-UNKNOWN	MTH 19-May-1999 LDG 0		12500	0	12500	10410
323000	ACTUATOR ASSEMBLY NOSE LANDING GEAR		*CF	1541900-3 331	MTH 19-May-1999 LDG 0		22500	0	22500	20410
<i>323001</i>										
323001	ACTUATOR ASSEMBLY LEFT MAIN LANDING GEAR		*CF	1541800-11 692	MTH 19-May-1999 LDG 0		12000	0	12000	9910
323002	ACTUATOR ASSEMBLY RIGHT MAIN LANDING GEAR		*CF	1541800-11 691	MTH 19-May-1999 LDG 0		12000	0	12000	9910
323003	NG UPLOCK ACTUATOR *CF			6327504-5 WMP333	MTH 19-May-1999		O/C			
323005	MLG UPLOCK ACTUATOR LEFT		*CF	6327504-4 W675	MTH 19-May-1999		O/C			
323005	MLG UPLOCK ACTUATOR RIGHT		*CF	6327504-4 W669	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
323006	HYD SHUTTLE VALVE	*CF		95784 625	MTH 19-May-1999		O/C			
324001 LEFT	MAIN LANDING GEAR WHEEL 9912398-7	SLC		3-1527-2 05740737	MTH 07-Feb-2008 HRS 2009 LDG 1565		O/C		0	
324001 RIGHT	MAIN LANDING GEAR WHEEL 9912398-2	SLC		3-1527-1 0992	MTH 29-Aug-2008 HRS 2150 LDG 1679		O/C		0	
324002 NOSE	LANDING GEAR WHEEL ASSY 9914069-2	SLC		3-1418 4809	MTH 24-Aug-2009 HRS 2314 LDG 1824		O/C		0	
324005 LEFT	MLG TIRE	SMF		026-528-0 1097S00505	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		O/C	0	0	0
324005 RIGHT	MLG TIRE	SLC		277K08-1 0160S00481	MTH 05-Nov-2010 HRS 2469.9 LDG 1977		O/C		0	
324007 NOSE	LANDING GEAR TIRE	SLC		030-611-0 8062W00832	MTH 24-Aug-2009 HRS 2314 LDG 1824		O/C		0	
324008 LEFT <i>324007 : L</i>	SHUTTLE VALVE	*CF		195-191-1 SN-UNKNOWN	MTH 19-May-1999		O/C			
324008 RIGHT	SHUTTLE VALVE	*CF		195-191-1 SN-UNKNOWN	MTH 19-May-1999		O/C			
324016 LEFT MAIN LANDING GEAR	BRAKE ASSY 9912398-8	SLC		2-1559-3 0720	MTH 09-Mar-2010 HRS 2381.1 LDG 1894		O/C		289	
324016 RIGHT MAIN LANDING GEAR	BRAKE ASSY 9912398-8	SLC		2-1559-3 1392	MTH 09-Mar-2010 HRS 2381.1 LDG 1894		O/C		289	
324101	POWER BRAKE AND ANTISKID VALVE 9912374-4	SLC		38-747 328	MTH 28-Apr-2008 HRS 2064		O/C		0	
324102 LEFT	ANTISKID TRANSDUCER ASSEMBLY 9912305-2	*CF		40-955 4434	MTH 19-May-1999		O/C			
324102 RIGHT	ANTISKID TRANSDUCER ASSEMBLY 9912305-2	*CF		40-955 4427	MTH 19-May-1999		O/C			
324103	BRAKE CONTROL BOX 9912305-6	*CF		42-707-1 1188	MTH 19-May-1999		O/C			
324104 LEFT	BRAKE CYLINDER ASSEMBLY 9912366-1	*CF		95805 843	MTH 19-May-1999		O/C			
324104 RIGHT	BRAKE CYLINDER ASSEMBLY 9912366-1	*CF		95805 848	MTH 19-May-1999		O/C			
324104A LEFT	BRAKE CYLINDER ASSEMBLY 9912366-2	*CF		95805-1 799	MTH 19-May-1999		O/C			
324104A RIGHT	BRAKE CYLINDER ASSEMBLY 9912366-2	*CF		95805-1 798	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
324105	PARKING BRAKE VALVE 9912388-1	*CF		95853 422A	MTH 19-May-1999		O/C			
324106	HYDRAULIC PUMP MOTOR	*CF		MP50B1 1230	MTH 19-May-1999		O/C			
324107	ANTISKID ACCUMULATOR	SLC		57C57663 0590	MTH 28-Apr-2008 HRS 2064		O/C	0		
324108	HYDRAULIC PRESSURE SWITCH 9912373-1	*CF		GPP1250-29 9852365	MTH 19-May-1999		O/C			
324109	BRAKE PRESSURE PUMP ASSY 9912364-2	*CF		640929 1149	MTH 19-May-1999		O/C			
324110	EMERGENCY BRAKE VALVE ASSY 9912387-2	SWF		878208-02 V160	MTH 07-Mar-2001 HRS 486		O/C	0		
324111 LEFT	MLG UP & LOCK SWITCH	*CF		65-430087 SN-UNKNOWN	MTH 19-May-1999		O/C			
324111 RIGHT	MLG UP & LOCK SWITCH	*CF		65-430087 SN-UNKNOWN	MTH 19-May-1999		O/C			
324111	NLG UP & LOCK SWITCH	*CF		65-430087 SN-UNKNOWN	MTH 19-May-1999		O/C			
324112	PRESSURE ANTISKID SWITCH 9912374-6	*CF		38-747502 444	MTH 19-May-1999		O/C			
325001	NOSE LANDING GEAR ASSEMBLY	*CF		6342000-22 187	MTH 19-May-1999		O/C			
325002	NOSE STEERING BUNGEE ASSEMBLY	*CF		5565624-19 SN-UNKNOWN	MTH 19-May-1999		O/C			
326001 LEFT	M/G DOWN&LOCK SWITCH	*CF		1EN118-6 SN-UNKNOWN	MTH 19-May-1999		O/C			
326001 RIGHT	M/G DOWN&LOCK SWITCH	*CF		1EN118-6 SN-UNKNOWN	MTH 19-May-1999		O/C			
326002	N/G DOWN&LOCK SWITCH	*CF		1EN118-6 SN-UNKNOWN	MTH 19-May-1999		O/C			
326006	EMERGENCY GEAR BOTTLE	SLC		9912368-2 4667	MTH 30-Jul-2010 HRS 2445.8 LDG 1949		288		31-Dec-2029	216 m 23 d
Manufacture Date: 31-Dec-2005										
326007	EMERGENCY GEAR GAUGE	*CF		18225901 66360A	MTH 19-May-1999		O/C			
330001 CENTER	PANEL LIGHTS DIMMER	*CF		273-1 992096	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
330001 LEFT	PANEL LIGHTS DIMMER	*CF		273-1 992082	MTH 19-May-1999		O/C			
330001 RIGHT	PANEL LIGHTS DIMMER	*CF		273-1 992080	MTH 19-May-1999		O/C			
330002	ELECTRICAL PANEL INVERTER	*CF		EM2044-1 2615A	MTH 19-May-1999		O/C			
332001 L1	INDIRECT LIGHTING INVERTER	*CF		6900113-3 2680	MTH 19-May-1999		O/C			
332002 L2	INDIRECT LIGHTING INVERTER	*CF		6900113-3 2660	MTH 19-May-1999		O/C			
332003 L3	INDIRECT LIGHTING INVERTER	*CF		6900113-3 2650	MTH 19-May-1999		O/C			
332004 L4	INDIRECT LIGHTING INVERTER	*CF		6900113-3 2661	MTH 19-May-1999		O/C			
332005 R1	INDIRECT LIGHTING INVERTER	*CF		6900113-3 2654	MTH 19-May-1999		O/C			
332006 R2	INDIRECT LIGHTING INVERTER	*CF		6900113-3 2671	MTH 19-May-1999		O/C			
332007 R3	INDIRECT LIGHTING INVERTER	*CF		6900113-3 2653	MTH 19-May-1999		O/C			
332008 R4	INDIRECT LIGHTING INVERTER	*CF		6900113-3 2670	MTH 19-May-1999		O/C			
334001	GROUND RECOGNITION LIGHT	*CF		90033-13 1903763	MTH 19-May-1999		O/C			
334003 LEFT	ANTI COLLISION POWER SUPPLY	*CF		04-1502-1408 9101	MTH 19-May-1999		O/C			
334003 RIGHT	ANTI COLLISION POWER SUPPLY	*CF		04-1502-1408 9337	MTH 19-May-1999		O/C			
334004 LEFT	HOUSING ASSY-LANDING LIGHT LAMP	*CF		50033011-1 672	MTH 19-May-1999		O/C			
334004 RIGHT	HOUSING ASSY-LANDING LIGHT LAMP	*CF		50033011-1 673	MTH 19-May-1999		O/C			
334005 LEFT	ANTI COLLISION LIGHT ASSY	SWF		03-1302-0003 13154	MTH 07-Mar-2001 HRS 486		O/C	0		
334005 RIGHT	ANTI COLLISION LIGHT ASSY	*CF		03-1302-0004 11170	MTH 19-May-1999		O/C			
334006	EMERGENCY EXIT BATTERY PACK	SMF		CBS28 1433	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
341001 LEFT	AIRSPD INDICATOR 9912446-4	*CF		37277-525 1100	MTH 19-May-1999		O/C			
341001 RIGHT	AIRSPD INDICATOR 9912446-4	*CF		37277-525 1124	MTH 19-May-1999		O/C			
341001	AOA COMPUTER	*CF		C12406-2 419	MTH 19-May-1999		O/C			
341008	AOA INDICATOR	*CF		C12405-1 426	MTH 19-May-1999		O/C			
341009	AOA SENSOR	*CF		C12417-2 428	MTH 19-May-1999		O/C			
341010 AFT	RADIO ALTIMETER ANTENNA *CF	*CF		S67-2002 13914	MTH 19-May-1999		O/C			
341010 FORWARD	RADIO ALTIMETER ANTENNA *CF	*CF		S67-2002 13919	MTH 19-May-1999		O/C			
341019 STANDBY	ENCODING ALTIMETER	SLC		44929-013 1732	MTH 21-May-2007 HRS 1849		O/C	0		
341020 LEFT	ADC/ALT UNIT AM-250			70251N02D04 02090830D	MTH 25-Oct-2006 HRS 1741		O/C	28		
341020 RIGHT	ADC/ALT UNIT AM-250	SLC		70251N02D04 02070758	MTH 20-May-2008 HRS 2081		O/C	755		
341020	REMOTE COURSE CONTROLLER RI-553	*CF		7016954-901 98100822	MTH 19-May-1999		O/C			
341029	MARKER BEACON INDICATOR KR-21	*CF		066-01021-0002 12177	MTH 19-May-1999		O/C			
341030	OAT INDICATOR	*CF		C307FCL A4468	MTH 19-May-1999		O/C			
342004 RIGHT	ATTITUDE DIRECTOR INDICATOR AD500A	MCO		7000836-927 93082660	MTH 14-Nov-2003 HRS 760		O/C	0		
342006	SLAVING ACCESSORY KA-51B	*CF		071-01242-0007 27877	MTH 19-May-1999		O/C			
342021 LEFT	VERTICAL SPEED INDICATOR *CF	*CF		C661006-0101 351963	MTH 19-May-1999		O/C			
342021 RIGHT	VERTICAL SPEED INDICATOR SLC	SLC		C661006-0101 720068E	MTH 22-Jul-2004 HRS 1058		O/C	0		
342042 LEFT	FLIGHT DIRECTOR MODE SELECTOR MS-560	*CF		7018341-905 99021378	MTH 19-May-1999		O/C			
342043 LEFT	VERTICAL GYRO VG-14A	*CF		7000622-901 98118724	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342043 RIGHT	VERTICAL GYRO VG-14A	*CF		7000622-901 98118739	MTH 19-May-1999		O/C			
342044	FLIGHT GUIDANCE COMPUTER IC-500	*CF		7017000-52105 99012172	MTH 19-May-1999		O/C			
342045	ACCELEROMETER AG-222	*CF		7000992 8193	MTH 19-May-1999		O/C			
342046	HORIZONTAL SITUATION INDICATOR KI525A	*CF		066-03046-0011 43731	MTH 19-May-1999		O/C			
342047	GYRO/SYNCHRONIZER ASSEMBLY	*CF		4019190-23 99016650	MTH 19-May-1999		O/C			
342048	YAW RATE GYRO RG-204	*CF		7007453-903 9014821	MTH 19-May-1999		O/C			
342049 LEFT	DIRECTIONAL GYRO C-14D	*CF		4020577-3 99016650	MTH 19-May-1999		O/C			
342049 RIGHT	DIRECTIONAL GYRO KG102A			060-00015-0001 X42326	MTH 08-Dec-2006 HRS 1770		O/C	0		
342050 RIGHT	FLUX DETECTOR KMT-112	*CF		071-01052-0000 56257	MTH 19-May-1999		O/C			
342050	FLUX DETECTOR FX-220	*CF		2594484 99013222	MTH 19-May-1999		O/C			
342052	DUAL REMOTE COMPENSATOR CS-412	*CF		2593379-001 99012776	MTH 19-May-1999		O/C			
342063	STANDBY JET GYRO AI-804	*CF		501-1197-09 6502	MTH 19-May-1999		O/C			
342064	STANDBY GYRO POWER SUPPLY SMF			501-1682-01 1450	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		O/C			
342066 LEFT BOTTOM	EHSI INDICATOR ED-600	*CF		7003430-901 98104263	MTH 19-May-1999		O/C			
342066 LEFT TOP	EADI INDICATOR ED-600	*CF		7003430-901 99024307	MTH 19-May-1999		O/C			
342067	MFD DISPLAY GARMIN MX-20 MFD			9200-19050-11 260007065	MTH 11-Mar-2005 HRS 1306		O/C	0		
342068	CONTROL DISPLAY DC-550	*CF		7016986-701 99021905	MTH 19-May-1999		O/C			
342071 NO. 2	TAWS ANNUNCIATION --	LNK		MD41-1128 C0411348	MTH 18-May-2004 HRS 986		O/C	0		
342071	TAWS ANNUNCIATOR 28VDC HORIZONTAL MOUNT	LNK		MD41-1128 C0411347	MTH 18-May-2004 HRS 986		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
342072	TAWS COMPUTER UNIT TAWS8000	LNK		805-18000-001 80243	MTH 18-May-2004 HRS 986		O/C	0		
344001	ANTENNA GLIDESLOPE COUPLER *CF			82-70-01 904	MTH 19-May-1999		O/C			
344004	ARRAY RADAR ANTENNA AA-2012V	*CF		071-01549-0200 2947	MTH 19-May-1999		O/C			
344005	RADAR TRANSCEIVER ART-2000	*CF		071-01519-0101 4248	MTH 19-May-1999		O/C			
344007	FMS CONFIGURATION MODULE *CF			071-00097-0100 5878	MTH 19-May-1999		O/C			
344021	RADIO MAGNETIC INDICATOR KNI-582	*CF		066-03060-0003 9515	MTH 19-May-1999		O/C			
344022	RADIO ALTIMETER RECEIVER/TRANSMITTER KRA-405B	*CF		066-01153-0101 1670	MTH 19-May-1999		O/C			
344023 NO. 1	DUAL NAVIGATION CONVERTER KN-40	*CF		066-01130-0701 11318	MTH 19-May-1999		O/C			
344024	RADIO ALTIMETER INDICATOR KNI-415	*CF		066-03031-0002 5294	MTH 19-May-1999		O/C			
345001 FORWARD	DME #1 ANTENNA *CF			56-80-01 7812	MTH 19-May-1999		O/C			
345002 NO. 1	DME RECEIVER/TRANSMITTER KN-63	*CF		066-01070-0001 14464	MTH 19-May-1999		O/C			
345003 RIGHT	DME INDICATOR KDI-574	*CF		066-01069-0014 72491	MTH 19-May-1999		O/C			
345005	MARKER BEACON ANTENNA *CF			31-10-01 2993	MTH 19-May-1999		O/C			
345006	GLIDESLOPE ANTENNA *CF			44-70-01 A6170	MTH 19-May-1999		O/C			
345011 NO. 2	ADF RECEIVER KR-87	*CF		066-01072-0007 68421	MTH 19-May-1999		O/C			
345012 NO. 1	ADF ANTENNA KA-44B	*CF		071-01234-0000 69189	MTH 19-May-1999		O/C			
345020 BOTTOM	VHF NAV 2 RECEIVER S3100-33/KN-53	*CF		066-01067-0004 71403	MTH 19-May-1999		O/C			
345020 TOP	VHF NAV 1 RECEIVER S3100-33/KN-53	*CF		066-01067-0004 71430	MTH 19-May-1999		O/C			
345021 LEFT	NAVIGATION INDICATOR KI-204	*CF		066-03034-0022 52797	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
345022 LEFT	NAVIGATION ANTENNA C598505-0303	*CF		22-37-101 2221	MTH 19-May-1999		O/C			
345022 RIGHT	NAVIGATION ANTENNA C598505-0303	*CF		22-37-101 2218	MTH 19-May-1999		O/C			
345034 NO. 1	TRANSPONDER KT-70	*CF		066-01141-1101 13787	MTH 19-May-1999		O/C			
345034 NO. 2	TRANSPONDER KT-70	36U		066-01141-1101 11596	MTH 07-Jan-2004 HRS 849		O/C	2211		
345038A	UNIVERSAL CONTROL DISPLAY UNIT MCO 8		8	1117-21 1188	MTH 28-Nov-2001 HRS 620		O/C	620		
345039 RIGHT	GPS 2 ANTENNA KA-92	*CF		071-01553-0200 5101	MTH 19-May-1999		O/C			
345046	FMS 1 COMPUTER UNS-1K S3100-175	U36		1116-40-1110 1068	MTH 05-Jul-2005 HRS 1392		O/C	1392		
346005	STORMSCOPE DISPLAY WX-950	*CF		805-10950-002 JSD12800229	MTH 19-May-1999		O/C			
346006	STORMSCOPE PROCESSER WX-1000	SWF		78-8051-9160-4 JXP10804057	MTH 14-May-2001 HRS 515		O/C	515		
346007 NO. 2	SKYWATCH ANTENNA NY-164	LNK		805-10890-001 82254	MTH 18-May-2004 HRS 986		O/C	0		
346007	STORMSCOPE ANTENNA WX-1000E	*CF		78-8051-9200-8 JSA07802207	MTH 19-May-1999		O/C			
346009 LEFT	AIR DATA COMPUTER S2800-475	SLC		962803-3-4-55-6407 B 1704	MTH 27-May-2004 HRS 1006		O/C	0		
346010	TEMP PROBE	SLC		681201-1 7433	MTH 23-Mar-2009 HRS 2251		O/C	0		
346012	CONVERTER -- RS232	SLC		933612-02 602	MTH 21-Nov-2005 HRS 1494		O/C	0		
346016	WSI INFLIGHT ANTENNA 420-ANTS-TD			009-E4670-00 3350	MTH 17-Jan-2008 HRS 2000		O/C	0		
346017	DATA TRANSFER UNIT PERMANENT DTU-100	SLC		1405-01-1 2088	MTH 04-Aug-2010 HRS 2445.8		O/C			
346029	SKYWATCH HP DISPLAY	LNK		805-11900-001 80731	MTH 18-May-2004 HRS 986		O/C	0		
346041	TCAS MODULE SKY HP	LNK		814-18005-001 81157	MTH 18-May-2004 HRS 986		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
349000	PASSIVE IRIDIUM GPS ANTENNA SLC			S67-1575-165 325	MTH 22-Jul-2004 HRS 1058		O/C	0		
350006	OXYGEN BOTTLE DOT-E 8162	*CF		176274-50 6280	MTH 19-May-1999		180	0	31-May-2014	29 m 23 d
350007	OXYGEN PRESSURE GAGE MD-97	*CF		C668512-0101 C98196	MTH 19-May-1999		O/C			
351002 COPILOT	OXYGEN MASK 9914067-41	SLC		MC10-15-109 69451	MTH 22-Nov-2010 HRS 2474.3 LDG 1982		72	0	30-Nov-2016	59 m 22 d
351002 PILOT	OXYGEN MASK 9914067-41	SLC		MC10-15-109 11324	MTH 10-Mar-2010 HRS 2381.9 LDG 1894		72	0	31-Mar-2016	51 m 23 d
351004 LEFT	ALTITUDE PRESSURE SWITCH 9912057-5	*CF		P24031 1978	MTH 19-May-1999		O/C			
351008	OXYGEN 3 POSITION VALVE 9912057-21	*CF		110081-06 503	MTH 19-May-1999		O/C			
361001 LEFT	TEMPERATURE SENSOR *CF			27431501-05 1AR10	MTH 19-May-1999		O/C			
361001 RIGHT	TEMPERATURE SENSOR *CF			27431501-05 6AR112	MTH 19-May-1999		O/C			
361002 LEFT	B/A PRECOOLER ASSEMBLY 9914402-2	*CF		8161-1 S4883T0648	MTH 19-May-1999		O/C			
361002 RIGHT	B/A PRECOOLER ASSEMBLY SMF			9914402-2 S4883T1794	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		O/C	0 0 0		
361004 LEFT	PNEUMATIC SHUTOFF VALVE ASSY 9912421-1	*CF		4713-2 670	MTH 19-May-1999		O/C			
361004 RIGHT	PNEUMATIC SHUTOFF VALVE ASSY 9912421-1	*CF		4713-2 686	MTH 19-May-1999		O/C			
361006	PRESSURE BLEED AIR REGULATOR 9912043-4	*CF		1H75-16 11AP63	MTH 19-May-1999		O/C			
361007 LEFT	OVER TEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 1821	MTH 19-May-1999		O/C			
361007 RIGHT	OVER TEMP BLEED AIR SWITCH 9914149-2	*CF		1173T181-2 1805	MTH 19-May-1999		O/C			
361007	DOOR SEAL CONTROL VALVE *CF			MJV3 SN-UNKNOWN	MTH 19-May-1999		O/C			
361008 LEFT	PRECOOLER DOOR VALVE *CF			5060-00-01 999	MTH 19-May-1999		O/C			
361008 RIGHT	PRECOOLER DOOR VALVE *CF			5060-00-01 1005	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
361009 LEFT	CHECK VALVE	*CF		1989-00-5 701	MTH 19-May-1999		O/C			
361009 RIGHT	CHECK VALVE	*CF		1989-00-5 690	MTH 19-May-1999		O/C			
361010 LEFT	CHECK VALVE	*CF		1553-00-18 1831	MTH 19-May-1999		O/C			
361010 RIGHT	CHECK VALVE	*CF		1553-00-18 2008	MTH 19-May-1999		O/C			
361011 LEFT	PRECOOLER ACTUATOR			6312213-5 SN-UNKNOWN	MTH 19-May-1999		O/C			
361012 RIGHT	PRECOOLER ACTUATOR			6312213-6 SN-UNKNOWN	MTH 19-May-1999		O/C			
522001	DOOR INFLATABLE SEAL 9912075-4	SLC		S15501-4 SN-UNKNOWN	MTH 21-Nov-2005 HRS 1494		O/C	0		
522002	SECONDARY SEAL	SLC		5511230-96 SN-UNKNOWN	MTH 21-Nov-2005 HRS 1494		O/C	0		
522003	ESCAPE HATCH SEAL	*CF		R441236 SN-UNKNOWN	MTH 19-May-1999		O/C			
522004	PRESSURE SWITCH	*CF		P18M-30 1737	MTH 19-May-1999		O/C			
531000 LEFT	TRUNNION SUPPORT FITTING	*CF		5513056-5 SN-UNKNOWN	MTH 19-May-1999 LDG 0		22500	0	22500	20410
531000 RIGHT	TRUNNION SUPPORT FITTING	*CF		5513056-6 SN-UNKNOWN	MTH 19-May-1999 LDG 0		22500	0	22500	20410
531001	ACTUATOR SUPPORT FITTING	*CF		6511105-1 SN-UNKNOWN	MTH 19-May-1999 LDG 0		22500	0	22500	20410
531201	RADOME ASSEMBLY	MCO		6313101-202 199	MTH 14-Nov-2003 HRS 760		O/C	0		
541001 LEFT ENGINE	INLET	*CF		6352100-56 SN-UNKNOWN	MTH 19-May-1999		O/C			
541001 RIGHT ENGINE	INLET	*CF		6352100-56 SN-UNKNOWN	MTH 19-May-1999		O/C			
561001 LEFT	WINDSHIELD 9912064-15	ICT		E149000-101 5663	MTH 12-May-2000 HRS 279		O/C	0		
561001 RIGHT	WINDSHIELD 9912064-16	ICT		E149000-102 5238	MTH 12-May-2000 HRS 279		O/C	279		
561002 L1	CABIN DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
561002 L2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 19-May-1999		O/C			
561002 L3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 19-May-1999		O/C			
561002 L4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 19-May-1999		O/C			
561002 R1	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 19-May-1999		O/C			
561002 R2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 19-May-1999		O/C			
561002 R3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 19-May-1999		O/C			
561002 R4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH 19-May-1999		O/C			
561003 PILOT	SIDE WINDOW	*CF		6311065-15 2089901	MTH 19-May-1999		O/C			
561004 COPILOT	SIDE WINDOW	*CF		6311065-16 1229901	MTH 19-May-1999		O/C			
571000 LEFT AFT	TRUNNION ATTACH FITTING	*CF		6322070-17 SN-UNKNOWN	MTH 19-May-1999 LDG 0		28300	0	28300	26210
571000 RIGHT AFT	TRUNNION ATTACH FITTING	*CF		6322070-16 SN-UNKNOWN	MTH 19-May-1999 LDG 0		28300	0	28300	26210
571001 LEFT FORWARD	TRUNNION ATTACH FITTING	*CF		6322060-15 SN-UNKNOWN	MTH 19-May-1999 LDG 0		28300	0	28300	26210
571001 RIGHT FORWARD	TRUNNION ATTACH FITTING	*CF		6322060-16 SN-UNKNOWN	MTH 19-May-1999 LDG 0		28300	0	28300	26210
571002 LEFT	SIDE BRACE FITTING	*CF		6322080-13 SN-UNKNOWN	MTH 19-May-1999 LDG 0		28300	0	28300	26210
571002 RIGHT	SIDE BRACE FITTING	*CF		6322080-14 SN-UNKNOWN	MTH 19-May-1999 LDG 0		28300	0	28300	26210
712001 LEFT ENGINE	AFT ISOLATER MOUNT 9912410-2	*CF		LM601SA4 SN-UNKNOWN	MTH 19-May-1999 HRS 0		3000	0	3000	403.5
712001 LEFT ENGINE FORWARD BOTTOM	ISOLATOR 9912410-3	*CF		LM601SA5 SN-UNKNOWN	MTH 19-May-1999 HRS 0		3000	0	3000	403.5
712001 LEFT ENGINE FORWARD TOP	ISOLATOR 9912410-3	SLC		LM601SA5 1421	MTH 21-Nov-2005 HRS 1494		3500	0	4994	2397.5
712001 RIGHT ENGINE	AFT ISOLATOR MOUNT 9912410-2	*CF		LM601SA4 SN-UNKNOWN	MTH 19-May-1999 HRS 0		3000	0	3000	403.5

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
712001 RIGHT ENGINE FORWARD BOTTOM	ISOLATOR 9912410-3	*CF		LM601SA5 SN-UNKNOWN	MTH 19-May-1999 HRS 0		3000	0	3000	403.5
712001 RIGHT ENGINE FORWARD TOP	ISOLATOR 9912410-3	SLC		LM601SA5 2755	MTH 21-Nov-2005 HRS 1494		3500	0	4994	2397.5
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 9912394-1/FJ44-A1	SLC		45700 1647	MTH 21-Nov-2005 HRS 1494		E/C	1494		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE 9912394-1/FJ44-A1	SLC		45700 1646	MTH 21-Nov-2005 HRS 1494		E/C	1494		
720007 E1	1ST LP TURBINE NOZZLE	SLC		57375 AU00533	MTH 21-Nov-2005 HRS 1494		O/C	1494		
720007 E2	1ST LP TURBINE NOZZLE	SLC		57375 AU00459	MTH 21-Nov-2005 HRS 1494		O/C	1494		
723001 E1 <i>720001 : E1**L</i>	FAN ROTOR	SLC		59070 AU00392	MTH 21-Nov-2005 HRS 1494 LDG 1069		16500	1069	16500	14410
723001 E2 <i>720001 : E2**R</i>	FAN ROTOR	SLC		59070 AU00389	MTH 21-Nov-2005 HRS 1494 LDG 1069		16500	1069	16500	14410
723010 E1 <i>725101 : E1**L</i>	HP COMPRESSOR ROTOR	SLC		59673 LC1362	MTH 21-Nov-2005 HRS 1494 LDG 1069		5000	1069	5000	2910
723010 E2 <i>725101 : E2**R</i>	HP COMPRESSOR ROTOR	SLC		59673 LC1305	MTH 21-Nov-2005 HRS 1494 LDG 1069		5000	1069	5000	2910
723015 E1 <i>720002 : E1**L</i>	IP COMPRESSOR ROTOR	SLC		66032 HW16587	MTH 21-Nov-2005 HRS 1494 LDG 1069		10000	694	10375	8285
723015 E2 <i>720002 : E2**R</i>	IP COMPRESSOR ROTOR	SLC		66032 HW16521	MTH 21-Nov-2005 HRS 1494 LDG 1069		10000	694	10375	8285
723022 E1 <i>720006 : E1**L</i>	DIFFUSER CASE ASSEMBLY	SLC		59906 AU00885	MTH 21-Nov-2005 HRS 1494		O/C	1494		
723022 E2 <i>720006 : E2**R</i>	DIFFUSER CASE ASSEMBLY	SLC		59906 AU00884	MTH 21-Nov-2005 HRS 1494		O/C	1494		
723061 E1 <i>720004 : E1**L</i>	HIGH PRESSURE SHAFT 200	SLC		55667 RX214	MTH 21-Nov-2005 HRS 1494		O/C	1494		
723061 E2 <i>720004 : E2**R</i>	HIGH PRESSURE SHAFT 200	SLC		55667 RX217	MTH 21-Nov-2005 HRS 1494		O/C	1494		
723092 E1 <i>720003 : E1**L</i>	COMPLETE LP SHAFT ASSEMBLY 40	SLC		50865 RX1SN1813	MTH 21-Nov-2005 HRS 1494		O/C	1494		
723092 E2 <i>720003 : E2**R</i>	COMPLETE LP SHAFT ASSEMBLY 40	SLC		50865 RX1SM9821	MTH 21-Nov-2005 HRS 1494		O/C	1494		
723149 E1 <i>720005 : E1**L</i>	HP COMPRESSOR COVER ASSY 260	SLC		56225 AU00959	MTH 21-Nov-2005 HRS 1494		O/C	1494		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
723149 E2 <i>720005 : E2**R</i>	HP COMPRESSOR COVER ASSY 260	SLC		56225 AU00965	MTH 21-Nov-2005 HRS 1494		O/C	1494		
724035 E1 <i>725102 : E1**L</i>	HP TURBINE ROTOR ASSEMBLY 320	SLC		59472 RRL0848	MTH 21-Nov-2005 HRS 1494		O/C	1494		
724035 E2 <i>725102 : E2**R</i>	HP TURBINE ROTOR ASSEMBLY 320	SLC		59472 RRL0843	MTH 21-Nov-2005 HRS 1494		O/C	1494		
724040 E1 <i>730003 : E1**L</i>	REAR FUEL SLINGER SEAL ASSEMBLY 280	SLC		55608 AU01944	MTH 21-Nov-2005 HRS 1494		O/C	1494		
724040 E2 <i>730003 : E2**R</i>	REAR FUEL SLINGER SEAL ASSEMBLY 280	SLC		55608 AU01928	MTH 21-Nov-2005 HRS 1494		O/C	1494		
725010 E1 <i>725103 : E1**L</i>	HP TURBINE DISK	SLC		59494 RRL7S00104	MTH 21-Nov-2005 HRS 1494 LDG 1069		8000	1490 1069	8004 8000	5407.5 5910
725010 E2 <i>725103 : E2**R</i>	HP TURBINE DISK	SLC		59494 RRL7S00102	MTH 21-Nov-2005 HRS 1494 LDG 1069		8000	1490 1069	8004 8000	5407.5 5910
725020 E1 <i>725501 : E1**L</i>	1ST LP TURBINE DISK 411	SLC		50255 RRL7S00199	MTH 21-Nov-2005 HRS 1494 LDG 1069		14700	1069	14700	12610
725020 E2 <i>725501 : E2**R</i>	1ST LP TURBINE DISK 411	SLC		50255 RRL7S00267	MTH 21-Nov-2005 HRS 1494 LDG 1069		14700	1069	14700	12610
725030 E1 <i>725502 : E1**L</i>	2ND LP TURBINE DISK 551	SLC		50792 RRL7S00167	MTH 21-Nov-2005 HRS 1494 LDG 1069		13500	1069	13500	11410
725030 E2 <i>725502 : E2**R</i>	2ND LP TURBINE DISK 551	SLC		50792 RRL7S00255	MTH 21-Nov-2005 HRS 1494 LDG 1069		13500	1069	13500	11410
726011 E1 <i>720008 : E1**L</i>	ACCESSORY DRIVE GEARBOX ASSEMBLY SLC			60570 WL02064	MTH 21-Nov-2005 HRS 1494		O/C	1494		
726011 E2 <i>720008 : E2**R</i>	ACCESSORY DRIVE GEARBOX ASSEMBLY SLC			60570 WL02058	MTH 21-Nov-2005 HRS 1494		O/C	1494		
730001 LEFT ENGINE	FUEL PRESSURE SWITCH 9912033-2	*CF		1103P0448 3851	MTH 19-May-1999		O/C			
730001 RIGHT ENGINE	FUEL PRESSURE SWITCH 9912033-2	*CF		1103P0448 3838	MTH 19-May-1999		O/C			
732002	SYNCHRONIZER CONTROLLER *CF			213693 12031268	MTH 19-May-1999		O/C			
732003	ENGINE SYNCHRONIZER ACTUATOR *CF			5485-066 12585606	MTH 19-May-1999		O/C			
733001 LEFT ENGINE	FUEL FLOW TRANSMITTER 9912417-1	SWF		1573-4 0704	MTH 05-Mar-2001 HRS 486		O/C	486		
733001 RIGHT ENGINE	FUEL FLOW TRANSMITTER 9912417-1	SWF		1573-4 0699	MTH 05-Mar-2001 HRS 486		O/C	486		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
730002 E1	FUEL NOZZLE ASSEMBLY 115	SLC		50817 BCC1ZR07908	MTH 21-Nov-2005 HRS 1494		O/C	1008		
730002 E2	FUEL NOZZLE ASSEMBLY 115	SLC		50817 BCCIUN08832	MTH 21-Nov-2005 HRS 1494		O/C	1494		
731001 E1 <i>731401 : E1**L</i>	FUEL PUMP 640	SLC		54904 YYK0952	MTH 21-Nov-2005 HRS 1494		3500	1494	3500	903.5
731001 E2 <i>731401 : E2**R</i>	FUEL PUMP 640	SLC		54904 YYK0951	MTH 21-Nov-2005 HRS 1494		3500	1494	3500	903.5
732090 E1 <i>732401 : E1**L</i>	START NOZZLE CONTROL VALVE 625	SLC		50803 RF12126606	MTH 21-Nov-2005 HRS 1494		3500	1494	3500	903.5
732090 E2 <i>732401 : E2**R</i>	START NOZZLE CONTROL VALVE 625	SLC		50803 RF12126610	MTH 21-Nov-2005 HRS 1494		3500	1494	3500	903.5
732301 E1	ELEC FUEL FILTER INDICATOR SLC	SLC		57847 GE0367	MTH 21-Nov-2005 HRS 1494		O/C	1494		
732301 E2	ELEC FUEL FILTER INDICATOR SLC	SLC		57847 GE0369	MTH 21-Nov-2005 HRS 1494		O/C	1494		
732401 E1 <i>732101 : E1**L</i>	FUEL CONTROL (HMU) UNIT 630	SLC		55629 RF12154092	MTH 21-Nov-2005 HRS 1494		3500	1494	3500	903.5
732401 E2 <i>732101 : E2**R</i>	FUEL CONTROL (HMU) UNIT 630	SLC		55629 RF12143676	MTH 21-Nov-2005 HRS 1494		3500	1494	3500	903.5
741010 E1 INBOARD <i>741001 : E1*LI</i>	IGNITION EXCITER SLC	SLC		56635 CK9800547	MTH 21-Nov-2005 HRS 1494		O/C	1494		
741010 E2 INBOARD <i>741001 : E2*RI</i>	IGNITION EXCITER SLC	SLC		56635 CK9800541	MTH 21-Nov-2005 HRS 1494		O/C	1494		
741020 E1 OUTBOARD <i>741001 : E1*LO</i>	IGNITION EXCITER SLC	SLC		56635 CK9800548	MTH 21-Nov-2005 HRS 1494		O/C	1494		
741020 E2 OUTBOARD <i>741001 : E2*RO</i>	IGNITION EXCITER SLC	SLC		56635 CK9800543	MTH 21-Nov-2005 HRS 1494		O/C	1494		
742001 E1	SHORT IGNITOR LEAD SLC	SLC		50852 SN-UNKNOWN	MTH 21-Nov-2005 HRS 1494		O/C	1494		
742001 E2	SHORT IGNITOR LEAD SLC	SLC		53279 SN-UNKNOWN	MTH 21-Nov-2005 HRS 1494		O/C	436		
742002 E1	LONG IGNITOR LEAD SLC	SLC		50853 SN-UNKNOWN	MTH 21-Nov-2005 HRS 1494		O/C	1494		
742002 E2	LONG IGNITOR LEAD SLC	SLC		50853 SN-UNKNOWN	MTH 21-Nov-2005 HRS 1494		O/C	1494		
742201 E1 INBOARD	IGNITOR 50424	SLC		CH31956 09044685	MTH 09-Mar-2010 HRS 2381.1 LDG 1894		O/C	0 0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
742201 E1 OUTBOARD	IGNITOR 50424	SLC		CH31956 SN-UNKNOWN	MTH 27-Jun-2008 HRS 2111		O/C	0		
742201 E2 INBOARD	IGNITOR 50424	SLC		CH31956 09044699	MTH 09-Mar-2010 HRS 2381.1 LDG 1894		O/C	0		
742201 E2 OUTBOARD	IGNITOR 50424	SLC		CH31956 SN-UNKNOWN	MTH 27-Jun-2008 HRS 2111		O/C	0		
771003 STANDBY	N1 INDICATOR 9912399-8			10272N05M00 B526	MTH 13-Feb-2007 HRS 1795		O/C	0		
771004	COMPUTER-N1			C-13232-1 891	MTH 15-Sep-2006 HRS 1700		O/C	0		
771005 E1 <i>771001 : E1**L</i>	N1 DUAL MAGNETIC SPEED SENSOR 740	SLC		50867 YYV513	MTH 21-Nov-2005 HRS 1494		O/C	1494		
771005 E2 <i>771001 : E2**R</i>	N1 DUAL MAGNETIC SPEED SENSOR 740	SLC		50867 YYV518	MTH 21-Nov-2005 HRS 1494		O/C	1494		
771015 E1 <i>771002 : E1**L</i>	N2 DUAL MAGNETIC SPEED SENSOR 750	SLC		50866 YYV459	MTH 21-Nov-2005 HRS 1494		O/C	1494		
771015 E2 <i>771002 : E2**R</i>	N2 DUAL MAGNETIC SPEED SENSOR 750	SLC		50866 YYV450	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E1 NO. 1	ITT PROBE 680	SLC		55334 YYF002197	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E1 NO. 2	ITT PROBE 681	SLC		55334 YYF002198	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E1 NO. 3	ITT PROBE 682	SLC		55334 YYF002199	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E1 NO. 4	ITT PROBE 710	SLC		55334 YYF002200	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E1 NO. 5	ITT PROBE	SLC		55334 YYF002201	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E1 NO. 6	ITT PROBE 712	SLC		55334 YYF002202	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E2 NO. 1	ITT PROBE 680	SLC		55334 YYF002191	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E2 NO. 2	ITT PROBE 681	SLC		55334 YYF002192	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E2 NO. 3	ITT PROBE 682	SLC		55334 YYF002193	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E2 NO. 4	ITT PROBE 710	SLC		55334 YYF002194	MTH 21-Nov-2005 HRS 1494		O/C	1494		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
772001 E2 NO. 5	ITT PROBE	SLC		55334 YYF002195	MTH 21-Nov-2005 HRS 1494		O/C	1494		
772001 E2 NO. 6	ITT PROBE 712	SLC		55334 YYF002196	MTH 21-Nov-2005 HRS 1494		O/C	1494		
781001 LEFT	EXHAUST NOZZLE	*CF		6352350-20 SN-UNKNOWN	MTH 19-May-1999		O/C			
781001 RIGHT	EXHAUST NOZZLE	*CF		6352350-20 SN-UNKNOWN	MTH 19-May-1999		O/C			
783001 LEFT	T/A SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 19-May-1999		O/C			
783001 RIGHT	T/A SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH 19-May-1999		O/C			
783002 LEFT	T/A PADDLE ASSY	*CF		6354051-79 SN-UNKNOWN	MTH 19-May-1999		O/C			
783002 RIGHT	T/A PADDLE ASSY	*CF		6354051-79 SN-UNKNOWN	MTH 19-May-1999		O/C			
783003 LEFT	ATTENUATOR ACTUATOR	*CF		6317105-10 SN-UNKNOWN	MTH 19-May-1999		O/C			
783003 RIGHT	ATTENUATOR ACTUATOR	*CF		6317105-10 SN-UNKNOWN	MTH 19-May-1999		O/C			
783005 LEFT	THRUST ATTENUATOR BELLCRANK	*CF		6354051-59 SN-UNKNOWN	MTH 19-May-1999		O/C			
783005 RIGHT	THRUST ATTENUATOR BELLCRANK	*CF		6354051-60 SN-UNKNOWN	MTH 19-May-1999		O/C			
793001	OIL TEMPERATURE/PRESSURE N2 SENSOR 9912399-9			10273N04M00 B534	MTH 21-Nov-2004 HRS 1193		O/C	0		
793002 LEFT ENGINE	OIL TEMPERATURE TRANSMITTER	*CF		MS28034-3 786	MTH 19-May-1999		O/C			
793002 RIGHT ENGINE	OIL TEMPERATURE TRANSMITTER	*CF		MS28034-3 826	MTH 19-May-1999		O/C			
793004 LEFT ENGINE	OIL PRESSURE TRANSMITTER 9912538-3	*CF		APTE-281A-1000-10 0G 5980639	MTH 19-May-1999		O/C			
793004 RIGHT ENGINE	OIL PRESSURE TRANSMITTER 9912538-3	*CF		APTE-281A-1000-10 0G 5980627	MTH 19-May-1999		O/C			
793006 LEFT ENGINE	OIL PRESSURE SWITCH 9912178-4	*CF		S1103P89-3 669	MTH 19-May-1999		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**

Aircraft Model: **525 - CITATION JET**

Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**

Airworthiness: **19-May-1999**

Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
793006 RIGHT ENGINE	OIL PRESSURE SWITCH 9912178-4	*CF		S1103P89-3 677	MTH 19-May-1999		O/C			
792201 E1	LUBE OIL COOLER	SLC		59866 PP0192	MTH 21-Nov-2005 HRS 1494		O/C	1494		
792201 E2	LUBE OIL COOLER	SLC		59866 PP0193	MTH 21-Nov-2005 HRS 1494		O/C	1494		
792401 E1	LUBE AND SCAVENGE PUMP	SLC		60689 WL01322	MTH 21-Nov-2005 HRS 1494		3500	1494	3500	903.5
792401 E2	LUBE AND SCAVENGE PUMP	SLC		60689 WL01321	MTH 21-Nov-2005 HRS 1494		3500	1494	3500	903.5
801101 LEFT ENGINE	STARTER/GENERATOR 9912125-2	SLC		300SGL129Q 1293XL2	MTH 03-Nov-2007 HRS 1956		1000	0	2956	359.5
801101 RIGHT ENGINE	STARTER/GENERATOR 9912125-2	SLC		300SGL129Q 2604XL2	MTH 31-Jan-2011 HRS 2513.3 LDG 2020		1000	0	3513.3	916.8



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-05-03 <i>05SL-03</i>	NEW 525 TASK BASED INSPECTION PROGRAM			MANDATORY	MTH 23-Oct-2006 HRS 1732		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-11-09 <i>11SB-09</i>	FUEL PLACARD RELOCATION			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 525-20-01 R18	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 525-20-05 <i>20SL-05</i>	ELECTRICAL CONNECTOR REPLACEMENT	SWF		RECOMMENDED	MTH 07-Sep-2001 HRS 581		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-21-15 <i>21SB-15</i>	BINARY PRESSURE SWITCH REPLACE	SWF		RECOMMENDED	MTH 07-Sep-2001 HRS 581		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-21-17 R2	FORWARD EVAPORATOR RELAY INSTALLATION			OPTIONAL			A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-21-17 <i>21SB-17</i>	FORWARD EVAPORATOR RELAY INSTALLATION			OPTIONAL	MTH		A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-21-19 <i>21SB-19</i>	TEMPERATURE SENSOR RELOCATION			OPTIONAL	MTH		A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
ASL 525-21-01 R1 <i>21SLA01 : 525R1</i>	AIR CONDITIONING - AIR CONDITIONING GROUND CABLE INSPECTION	SWF		MANDATORY	MTH 04-Oct-2001 HRS 589		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-23-08 <i>23SB-08</i>	ALLIEDSIGNAL 8.33 KHZ COMMUNICATION RADIO INSTALLATION			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-23-12 <i>23SB-12</i>	HONEYWELL KY-196A/KY-196B DUAL VHF COMMUNICATION SYSTEM UPGRADE	SLC		RECOMMENDED	MTH HRS		300			
<b>State : OPEN</b>	<b>MOC :</b>									
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-23-13 <i>23SB-13</i>	GARMIN RADIO REPLACEMENT			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 525-23-04 <i>23SL-04</i>	TRANSMITTAL OF LOCKHEED MARTIN SB A200S SSCVR FSB007, NEW SOFTWARE PROGRAM INCORPORATED INTO MAIN PROCESSOR PRINTED WIRING ASSEMBLY, P/N 205E0976-XX	ICT		INFORMATIONAL	MTH 12-May-2000 HRS 279		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SL 525-23-05 <i>23SL-05</i>	TRANSMITTAL OF ALLIED SIGNAL BENDIX/KING SERVICE BULLETIN KY196A-9 - KY196A VHF COMM TRANSCEIVER	ICT		RECOMMENDED	MTH 12-May-2000 HRS 279		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-23-06 23SL-06	TRANSMITTAL OF ALLIED SIGNAL BENDIX/KING SERVICE BULLETIN KY196B-2 - KY196B VHF COMM TRANSCEIVER	ICT		RECOMMENDED	MTH 12-May-2000 HRS 279		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
SB 525-24-07 R2 24SB-07 : 525R2	44 AMP HOUR BATTERY INSTALLATION	SLC		OPTIONAL	MTH 31-Jan-2011 HRS 2513.3 LDG 2020		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-24-19 R2 24SB-19 : 525R2	CONCORDE LEAD ACID BATTERY INSTALLATION			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-24-22 24SB-22	TAILCONE ELECTRICAL GROUND STUD IMPROVEMENT	SLC		RECOMMENDED	MTH 28-Jul-2004 HRS 1058		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-24-23 24SB-23	AFT CABIN WIRE BUNDLE PROTECTION	SLC		RECOMMENDED	MTH 28-Jul-2004 HRS 1058		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-24-25 24SB-25	NICKEL-CADMIUM BATTERY INSTALLATION			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 525-24-03 24SL-03	IGNITER CONTROL PRINTED/CIRCUIT BOARD INSPECTION	ICT		RECOMMENDED	MTH 27-Nov-2001 HRS 620		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-25-22 R1 25SB-22 : 525R1	GLARESHIELD LEATHER STRAP INSTALLATION			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-25-23 R1	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION			OPTIONAL					A/R	
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-25-23 25SB-23	THREE FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) WITH NAVIGATION INTERFACE INSTALLATION			OPTIONAL					A/R	
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-25-26 25SB-26	PASSENGER SEAT GEAR AND BACKREST LATCH PIN REPLACEMENT			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 525-25-03 R1 25SL-03 : 525R1	LEFT HAND TOILET SEAT BELT INSPECTION/INSTALLATION	ICT		RECOMMENDED	MTH 12-May-2000 HRS 279		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
SL 525-25-05 25SL-05	INSPECTION OF THE BACKREST LATCH PLATES	SLC		MANDATORY	MTH 05-Nov-2010 HRS 2469.9 LDG 1977		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-26-01 26SB-01	FIRE BOTTLE IDENTIFICATION SLEEVE INSTALLATION	SLC		MANDATORY	MTH 12-May-2005 HRS 1357		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-27-11 R2 <i>27SB-11 : 525R2</i>	STEEP APPROACH CERTIFICATION-SPEED BRAKE SWITCH ADJUSTMENT	*CF		OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-27-15 R1 <i>27SB-15 : 525R1</i>	FLAP OVERRIDE SWITCH INSTALLATION	SLC		RECOMMENDED	MTH 12-Dec-2005 HRS 1508		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-27-17 <i>27SB-17</i>	ELECTRIC ELEVATOR TRIM PRINTED CIRCUIT BOARD REPLACEMENT	SLC		MANDATORY	MTH 26-Mar-2004 HRS 944		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-27-18 <i>27SB-18</i>	ELEVATOR TRIM POINTER IMPROVEMENT			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-27-19 R1	ELEVATOR TRIM CABLE THICKNESS CHANGE AND VERTICAL STABILIZER CABLE FAIRLEAD INSTALLATION			MANDATORY	MTH HRS		36 1200		13-Sep-2013 3650.78	21 m 5 d 1054.28
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-27-20 <i>27SB-20</i>	ELEVATOR TRIM POINTER ASSEMBLY IMPROVEMENT			OPTIONAL	MTH		A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
ASL 525-27-02 <i>27SLA02</i>	ELECTRIC ELEVATOR TRIM RUNAWAY PROCEDURE	MCO		MANDATORY	MTH 14-Nov-2003 HRS 760		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
SL 525-27-01 <i>27SL-01</i>	ELEVATOR ELECTRIC TRIM TAB ACTUATOR MOUNT INSPECTION			RECOMMENDED	MTH 04-Apr-2003 HRS 709		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SL 525-27-04 <i>27SL-04</i>	FLAP PUSHROD SAFETY WIRE INSPECTION	SLC		RECOMMENDED	MTH 26-Mar-2008 HRS 2029		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-28-10 <i>28SB-10</i>	FUEL CROSSFEED TO FUEL TRANSFER MODIFICATION			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-28-11 R1 <i>28SB-11 : 525R1</i>	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	SLC		MANDATORY	MTH 07-Dec-2004 HRS 1204		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
SB 525-28-12 <i>28SB-12</i>	WING FUEL BOOST PUMP WIRE IMPROVEMENT	SLC		MANDATORY	MTH 28-Jul-2004 HRS 1058		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-29-09 <i>29SB-09</i>	HYDRAULIC LINE IMPROVEMENT	SWF		MANDATORY	MTH 05-Mar-2001 HRS 486		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-29-10 <i>29SB-10</i>	SOLENOID LOADING VALVE REPLACEMENT			RECOMMENDED	MTH 04-Apr-2003 HRS 709		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-29-11 R2 <i>29SB-11 : 525R2</i>	HYDRAULIC RELIEF VALVE INSPECTION			CANCELLED	MTH HRS		36 1200			
<b>State : OPEN</b>	<b>MOC :</b>									
SERVICE BULLETIN CANCELLED.										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-29-14 R1	HYDRAULIC POWER - HYDRAULIC RELIEF VALVE STAKING IMPROVEMENT	SMF		MANDATORY	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		A/R			Complete
<b>State :</b> CLOSED	<b>MOC :</b> COMPLIED WITH									
SB 525-29-15	HYDRAULIC POWER - STAINLESS STEEL TUBE ASSEMBLY INSTALLATION			OPTIONAL			A/R			
<b>State :</b> OPEN	<b>MOC :</b>									
SB 525-30-07 R2 30SB-07 : 525R2	WING ANTI-ICE OVERTEMPERATURE SWITCH RELOCATION			OPTIONAL	MTH		A/R			
<b>State :</b> OPEN	<b>MOC :</b>									
SB 525-32-20 32SB-20	LANDING GEAR BRAKE LINE REPLACEMENT AND RELOCATION	SWF		RECOMMENDED	MTH 02-May-2001 HRS 507		A/R			Complete
<b>State :</b> CLOSED	<b>MOC :</b> COMPLIED WITH									
SB 525-32-22 32SB-22	EMERGENCY GEAR RELEASE BRACKET CLEARANCE IMPROVEMENT			RECOMMENDED	MTH 04-Apr-2003 HRS 709		A/R			Complete
<b>State :</b> CLOSED	<b>MOC :</b> COMPLIED WITH									
SB 525-32-25 32SB-25	BEARING REPLACEMENT	SLC		MANDATORY	MTH 25-Jul-2006 HRS 1664		A/R			N/A
<b>State :</b> CLOSED	<b>MOC :</b> NOT APPLICABLE - NOT APPLICABLE									
ASL 525-32-21 32SLA21	TRANSMITTAL OF GOODRICH SERVICE BULLETIN 2-1559-32-4, MAIN LANDING GEAR - BRAKE ASSEMBLY - P/N'S 2-1559-1 AND 2-1559-2 - CESSNA CITATION AIRCRAFT - INTRODUCTION OF A NEW BRAKE ASSEMBLY P/N 2-1559-3	SLC		MANDATORY	MTH 09-Mar-2010 HRS 2381.1 LDG 1894		A/R			Complete
<b>State :</b> CLOSED	<b>MOC :</b> COMPLIED WITH									
SL 525-32-15 32SL-15	NOSE LANDING GEAR TIRE INSPECTION	MCO		MANDATORY	MTH 14-Nov-2003 HRS 760 LDG 375		A/R			Complete
<b>State :</b> CLOSED	<b>MOC :</b> COMPLIED WITH									
SL 525-32-17 R1 32SL-17 : 525R1	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH		-			
<b>State :</b> OPEN	<b>MOC :</b>									
SL 525-32-19 32SL-19	TRANSMITTAL OF GOODRICH SERVICE LETTER 2056	SLC		RECOMMENDED	MTH 03-Nov-2007 HRS 1956		A/R			Complete
<b>State :</b> CLOSED	<b>MOC :</b> COMPLIED WITH									
SL 525-32-20 32SL-20	MAIN LANDING GEAR DOOR PUSHROD SAFETY WIRE INSPECTION	SLC		RECOMMENDED	MTH 26-Mar-2008 HRS 2029		A/R			Complete
<b>State :</b> CLOSED	<b>MOC :</b> COMPLIED WITH									
SL 525-32-23 R2 32SL-23	EMERGENCY GEAR RELEASE INSPECTION	SMF		MANDATORY	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		-			Complete
<b>State :</b> CLOSED	<b>MOC :</b> COMPLIED WITH									
SB 525-33-07 33SB-07	CHART LIGHT MODIFICATION			OPTIONAL	MTH		-			
<b>State :</b> OPEN	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB 525-34-30 R1 <i>34SB-30 : 525R1</i>	ART 2000-6 RADAR MODIFICATION ICT			RECOMMENDED	MTH 12-May-2000 HRS 279		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.</b>									
SB 525-34-36 <i>34SB-36</i>	UNS-1K W/604.0 SOFTWARE UPGRADE ICT			RECOMMENDED	MTH 28-Nov-2000 HRS 433		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-34-38 <i>34SB-38</i>	SHADIN ADC-200 FUEL/AIR DATA COMPUTER RECOMMENDED				MTH 04-Apr-2003 HRS 709		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-34-41 R1 <i>34SB-41 : 525R1</i>	REDUCED VERTICAL SEPARATION (RVSM) OPERATION MODIFICATION LNK			OPTIONAL	MTH 18-May-2004 HRS 986		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-34-46 <i>34SB-46</i>	UNIVERSAL AVIONICS FLAT PANEL CONTROL DISPLAY UNIT UPGRADE TO MOD 8 MCO			MANDATORY	MTH 14-Nov-2003 HRS 760		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-34-61 <i>34SB-61</i>	MST-67A TRANSPONDER INSTALLATION OPTIONAL				MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-34-62 R1 <i>34SB-62 : 525R1</i>	GARMIN RADIO INSTALLATION OPTIONAL				MTH		A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
ASL 525-34-13 <i>34SLA13</i>	FLAT PANEL CONTROL DISPLAY UNIT INVERTER CIRCUITRY INTEGRITY TEST ICT			MANDATORY	MTH 27-Nov-2001 HRS 620		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SL 525-34-08 <i>34SL-08</i>	TRANSMITTAL OF BFGOODRICH ALERT SERVICE BULLETIN 78A ICT			MANDATORY	MTH 19-May-1999 HRS 13		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SL 525-34-09 <i>34SL-09</i>	TRANSMITTAL OF BF GOODRICH ALERT SERVICE BULLETIN #79 SWF			MANDATORY	MTH 24-Dec-1999 HRS 157		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SL 525-34-10 R1 <i>34SL-10 : 525R1</i>	GNS-XLS MOD 7 SOFTWARE UPGRADE SLC			RECOMMENDED	MTH 26-Mar-2004 HRS 944		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
SL 525-34-14 R1 <i>34SL-14 : 525R1</i>	TRANSMITTAL OF HONEYWELL SERVICE BULLETIN IN 182A-16 RADAR INDICATOR SLC			RECOMMENDED	MTH 26-Mar-2004 HRS 944		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SLA 525-34-04 <i>34SLA04</i>	KLN89B,KLN90B & KLN900 GPS INSTRUMENT LANDING SYSTEM APPROACH RESTRICTIONS SWF			MANDATORY	MTH 24-Dec-1999 HRS 157		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SL 525-35-02 <i>35SL-02</i>	PORTABLE OXYGEN CYLINDER MASK INSPECTION/REPLACEMENT SWF			RECOMMENDED	MTH 07-Sep-2001 HRS 581		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-35-05	OXYGEN - OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 525-35-06	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	SMF		MANDATORY	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		-			N/A
<b>State : CLOSED</b>	<b>MOC : NOT APPLICABLE - BOTH MASKS DO NOT FALL INTO THE SUSPECT CATEGORY DUE TO P/N &amp; S/N</b>									
SB 525-36-04 R1 36SB-04 : 525R1	PRECOOLER IMPROVEMENT			DISCRETIONARY	MTH		A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 525-36-01L R1 LEFT 36SL-01 : L	PRECOOLER INSPECTION MODEL 525			RECOMMENDED	MTH 19-Oct-2006 HRS 1732		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SL 525-36-01R R1 RIGHT 36SL-01 : R	PRECOOLER INSPECTION			RECOMMENDED	MTH 19-Oct-2006 HRS 1732		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-52-07 52SB-07	TAILCONE BAGGAGE DOOR UPPER DOOR LATCH DRAIN			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-52-08 R1 52SB-08 : 525R1	IMPROVEMENT FOR THE CABIN ENTRY STEPS			OPTIONAL	MTH		A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-52-09 R1	CABIN ENTRY DOOR HANDLE POSITION SWITCH INSTALLATION			OPTIONAL			A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
ASL 525-52-01 52SLA01	EMERGENCY DOOR INSPECTION			MANDATORY	MTH 10-Dec-2007 HRS 1982		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-53-07 R2 53SB-07 : 525R2	AFT BAGGAGE SECTION SKI OPTION INSTALLATION			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-53-18 53SB-18	RIVET INSPECTION/INSTALLATION	SWF		RECOMMENDED	MTH 07-Sep-2001 HRS 581		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-53-20 R1 53SB-20 : 525R1	DISABLE THE COCKPIT MOUNTED RELIEF TUBE(S)	TOL		MANDATORY	MTH 20-Jun-2007 HRS 1863		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
ASL 525-53-03 53SLA03	RELIEF TUBE CORROSION			MANDATORY	MTH 18-Dec-2006 HRS 1773		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
ASL 525-53-04 R1 53SLA04 : 525R1	RELIEF TUBE CORROSION INSPECTION	TOL		MANDATORY	MTH 20-Jun-2007 HRS 1863		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SL 525-53-05 53SL-05	INTERCOSTAL DRAINAGE PATH INSPECTION			RECOMMENDED	MTH HRS		300		2663	66.5
<b>State : OPEN</b>	<b>MOC :</b>									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SL 525-53-06	UPPER TAILCONE SKIN INSPECTION	KSLC		MANDATORY	MTH 28-Jul-2011 HRS 2569 LDG 2067		A/R			Complete
<b>State : CLOSED</b>		<b>MOC : COMPLIED WITH</b>								
SB 525-54-04 R2	NACELLES/PYLONS - FIREWALL BOX REPAIR			RECOMMENDED			A/R			
<b>State : OPEN</b>		<b>MOC :</b>								
SB 525-54-05	NACELLES/PYLONS - MID FIREWALL FASTENER INSPECTION	SMF		MANDATORY	MTH 07-Dec-2011 HRS 2596.5 LDG 2090		A/R			N/A
<b>State : CLOSED</b>		<b>MOC : NOT APPLICABLE - ORIGINAL ISSUE OR REVISION 1 OF SB525-54-04 HAS NOT BEEN COMPLIED WITH, THEREFORE SB525-54-05 IS NOT APPLICABLE PER SERIAL NUMBER EFFECTIVITY OF THIS SERVICE BULLETIN</b>								
SB 525-57-12 57SB-12	LEADING EDGE TUBE REPLACEMENT	SWF		RECOMMENDED	MTH 04-Apr-2003 HRS 709		-			Complete
<b>State : CLOSED</b>		<b>MOC : COMPLIED WITH</b>								
SL 525-57-02 57SL-02	ACCESS DOOR DRAINAGE IMPROVEMENT	SLC		RECOMMENDED	MTH 25-Jul-2006 HRS 1664		-			Complete
<b>State : CLOSED</b>		<b>MOC : COMPLIED WITH</b>								
SL 44-71-153 E1	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING						-			
<b>State : OPEN</b>		<b>MOC :</b>								
SL 44-71-153 E2	ENGINE - VOLCANIC ASH - CONTAMINATION / TROUBLESHOOTING						-			
<b>State : OPEN</b>		<b>MOC :</b>								
SL 525-72-09 72SL-09	TRANSMITTAL OF WILLIAMS ROLLS SERVICE BULLETIN FJ44-72-052, ENGINE-IP COMPRESSOR ROTOR-REPLACE	MCO		MANDATORY	MTH 05-Nov-2003 HRS 760		-			Complete
<b>State : CLOSED</b>		<b>MOC : COMPLIED WITH</b>								
SB FJ44-72-029 R3 E1	1ST LP TURBINE NOZZLE ASSEMBLY-ADD OIL SCAVENGE SLOT			RECOMMENDED			-			
<b>State : OPEN</b>		<b>MOC :</b>								
SB FJ44-72-029 R3 E2	1ST LP TURBINE NOZZLE ASSEMBLY-ADD OIL SCAVENGE SLOT			RECOMMENDED			-			
<b>State : OPEN</b>		<b>MOC :</b>								
SB FJ44-72-051 R3 E1	REWORK NAMEPLATE			RECOMMENDED	HRS LDG		DUE DUE DUE		2994.9 2819	398.4 729
<b>State : OPEN</b>		<b>MOC :</b>								
SB FJ44-72-051 R3 E2	REWORK NAMEPLATE			RECOMMENDED	HRS LDG		DUE DUE DUE		2994.9 2819	398.4 729
<b>State : OPEN</b>		<b>MOC :</b>								
SB FJ44-72-054 R4 E1	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED			-			
<b>State : OPEN</b>		<b>MOC :</b>								

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-054 R4 E2	ENGINE - GEARBOX ASSEMBLY - INCORPORATE NEW FUEL PUMP ADAPTER			RECOMMENDED			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-066 R3 E1	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE			RECOMMENDED			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-066 R3 E2	ENGINE - CARBON RING SEAL AND BEARING HOUSING - REPLACE			RECOMMENDED			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-076 E1	REWORK - ENGINE- COMPRESSOR STATOR			OPTIONAL	HRS LDG		DUE DUE DUE		2994.9 2819	398.4 729
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-076 E2	REWORK - ENGINE- COMPRESSOR STATOR			OPTIONAL	HRS LDG		DUE DUE DUE		2994.9 2819	398.4 729
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-079 R2 E1	ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			INFORMATIONAL			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-079 R2 E2	ENGINE - MPI - TIME EXTENSION FOR TAP ENGINES			INFORMATIONAL			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-083 R1 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-083 R1 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-083 R3 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL	LDG		-		2819	729
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-083 R3 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL	LDG		-		2819	729
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-083 R4 E1	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL	HRS LDG		-		2994.9 2819	398.4 729
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-083 R4 E2	ENGINE- UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION			OPTIONAL	HRS LDG		-		2994.9 2819	398.4 729
<b>State : OPEN</b>	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-72-087 R2 E1	ENGINE - BLEED VALVE SHAFT - REPLACE			OPTIONAL			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-087 R2 E2	ENGINE - BLEED VALVE SHAFT - REPLACE			OPTIONAL			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-087 R3 E1	ENGINE - BLEED VALVE SHAFT - REPLACE			OPTIONAL	LDG		-		2819	729
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-087 R3 E2	ENGINE - BLEED VALVE SHAFT - REPLACE			OPTIONAL	LDG		-		2819	729
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-087 R4 E1	ENGINE - BLEED VALVE SHAFT - REPLACE			OPTIONAL	HRS LDG		-		2994.9 2819	398.4 729
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-087 R4 E2	ENGINE - BLEED VALVE SHAFT - REPLACE			OPTIONAL	HRS LDG		-		2994.9 2819	398.4 729
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-092 E1	ENGINE - 1ST LP TURBINE NOZZLE - REWORK			RECOMMENDED			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB FJ44-72-092 E2	ENGINE - 1ST LP TURBINE NOZZLE - REWORK			RECOMMENDED			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 44-72-306 R1 E1	ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 44-72-306 R1 E2	ENGINE - LP REAR BEARING SEAL RETAINER - REPLACE			RECOMMENDED			-			
<b>State : OPEN</b>	<b>MOC :</b>									
ASL 525-73-06L <i>73ASL06 : E1**L</i>	TRANSMITTAL OF WILLIAMS-ROLLS ALERT SERVICE BULLETIN FJ44-A73-12 ENGINE FUEL CONTROL UNION-TO-OIL COOLER FUEL TUBE ASSEMBLY - REPLACE	SWF		RECOMMENDED	MTH 24-Dec-1999 HRS 157		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
ASL 525-73-06R <i>73ASL06 : E2**R</i>	TRANSMITTAL OF WILLIAMS-ROLLS ALERT SERVICE BULLETIN FJ44-A73-12 ENGINE FUEL CONTROL UNION-TO-OIL COOLER FUEL TUBE ASSEMBLY - REPLACE	SWF		RECOMMENDED	MTH 24-Dec-1999 HRS 157		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB 525-76-05 R1 <i>76SB-05 : 525R1</i>	ENGINE POWER CONTROL CABLE REPLACEMENT			OPTIONAL	MTH		-			
<b>State : OPEN</b>	<b>MOC :</b>									
SB 525-76-06 <i>76SB-06</i>	SAFE FLIGHT N1 COMPUTER INSTALLATION			OPTIONAL	MTH 15-Sep-2006 HRS 1700		-			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
SB FJ44-77-008 R3 E1	ENGINE INDICATING - REPLACE ITT PROBES WITH MID-LENGTH PROBE HARNESS			RECOMMENDED			-			
<b>State : OPEN</b>	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
SB FJ44-77-008 R3 E2	ENGINE INDICATING - REPLACE ITT PROBES WITH MID-LENGTH PROBE HARNESS			RECOMMENDED						
<b>State : OPEN</b>	<b>MOC :</b>									
SL 525-99-05	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
<b>State : OPEN</b>	<b>MOC :</b>									
SL 525-99-06	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
<b>State : OPEN</b>	<b>MOC :</b>									



# CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

## Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
AD 2006-16-18 <i>34AD-12</i>	SANDEL AVIONICS INCORPORATED MODEL ST3400 TERRAIN AWARENESS WARNING SYSTEM/RADIO MAGNETIC INDICATOR(TAWS/RMI)			MANDATORY	MTH 29-Nov-2006 HRS 1764		A/R			N/A
<b>State : CLOSED</b>	<b>MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
AD 2005-17-11 <i>26AD-01</i>	PREVENT INCORRECT INSTALLATION OF WIRES	SLC		MANDATORY	MTH 21-Nov-2005 HRS 1494		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH.</b>									
AD 2001-23-17 <i>34AD-04</i>	GARMIN GNS 430	SWF		MANDATORY	MTH 08-Nov-2002 HRS 649		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
AD 2002-20-09 <i>31AD-01</i>	COLLINS AFD-3010 AFD UNITS	SWF		MANDATORY	MTH 08-Nov-2002 HRS 649		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED</b>									
AD 2003-13-08 <i>34AD-05</i>	TAWS 8000 TERRAIN AWARENESS	SLC		MANDATORY	MTH 28-Jun-2004 HRS 1045		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
AD 2004-08-15 <i>34AD-06</i>	TAWS 8000 TERRAIN AWARENESS	SLC		MANDATORY	MTH 28-Jun-2004 HRS 1045		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - NOT APPLICABLE</b>									
AD 1999-08-21 <i>35AD-01</i>	PURITAN-BENNETT AERO SYSTEM	SWF		MANDATORY	MTH 24-Dec-1999 HRS 157		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									
AD 2008-03-10 <i>53AD-01</i>	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE	SLC		AIRWORTHINESS	MTH 26-Mar-2008 HRS 2029		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH - PREVIOUSLY COMPLIED WITH.</b>									
AD 1999-07-04 <i>E1</i> <i>71AD-01 : E1**L</i>	TO PREVENT HIGH PRESSURE TURBINE (HPT) DISK RIM FAILURE (P/N 55291)	SLC			MTH 03-Nov-2007 HRS 1956 LDG 1514		A/R			N/A
<b>State : CLOSED</b>	<b>MOC : NOT APPLICABLE - NOT APPLICABLE BY COMPONENT PART NUMBER.</b>									
AD 1999-07-04 <i>E2</i> <i>71AD-01 : E2**R</i>	TO PREVENT HIGH PRESSURE TURBINE (HPT) DISK RIM FAILURE (P/N 55291)	SLC			MTH 03-Nov-2007 HRS 1956 LDG 1514		A/R			N/A
<b>State : CLOSED</b>	<b>MOC : NOT APPLICABLE - NOT APPLICABLE BY COMPONENT PART NUMBER.</b>									
AD 2004-14-20 <i>27AD-02</i>	CORRECT SINGLE POINT FAILURE IN THE ELECTRIC PITCH TRIM SYSTEM			MANDATORY	MTH 27-Sep-2004 HRS 1120		A/R			Complete
<b>State : CLOSED</b>	<b>MOC : COMPLIED WITH</b>									



## CESCOM 10 - Aircraft Status Report

Owner: **J.M. THOMAS FOREST PRODUCTS**  
 Aircraft Model: **525 - CITATION JET**  
 Aircraft Serial: **525-0316** Unit: **0316** Reg No: **N458MT**  
 Airworthiness: **19-May-1999**  
 Print Date: **08-Dec-2011 8:36AM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
<b>AIRCRAFT</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 1</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>ENG 2</b>	<b>2596.5</b>	<b>2090</b>	<b>07-Dec-2011</b>	<b>.22</b>
<b>AIR COND</b>	<b>765.2</b>		<b>07-Dec-2011</b>	<b>.9</b>

### Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	DUE 1 DUE 2	Remains Remains
25FO-01 525/D <i>25FO-01 : 525/D</i>	REFRESH CTR-LH FWD DELUXE(EXCH) FACTORY OPTION	*CF		128D FO	MTH 19-May-1999		-			
25FO-05 525/B <i>25FO-05 : 525/B</i>	LOCATOR BEACON ARTEX FACTORY OPTION	*CF		175B FO	MTH 19-May-1999		-			
25FO-06 525 <i>25FO-06 : 525</i>	STANDARD SEATING FACTORY OPTION	*CF		109 FO	MTH 19-May-1999		-			
25FO-13 525/F <i>25FO-13 : 525/F</i>	CURTAIN, AFT REMOVABLE(EXCH) FACTORY OPTION	*CF		121F FO	MTH 19-May-1999		-			
25FO-18 525/C <i>25FO-18 : 525/C</i>	MONORAIL SUNVISOR(EXCH) FACTORY OPTION	*CF		122C FO	MTH 19-May-1999		-			
25FO-37 525/Q <i>25FO-37 : 525/Q</i>	OVERBOARD DRAIN, LH FWD RELIEF TUBE FACTORY OPTION	*CF		131Q FO	MTH 19-May-1999		-			
25FO-50 G <i>25FO-50 : G</i>	PSU ACCENT STRIP - DARK PEBBLE FACTORY OPTION	*CF		730G FO	MTH 19-May-1999		-			
25FO-51 525/G <i>25FO-51 : 525/G</i>	HEADLINER, TROON BIRCH FACTORY OPTION	*CF		725G FO	MTH 19-May-1999		-			
25FO-54 525/T <i>25FO-54 : 525/T</i>	TAILCONE BAGGAGE CARPET FACTORY OPTION	*CF		136T FO	MTH 19-May-1999		-			
25FO-59 525/L <i>25FO-59 : 525/L</i>	PILLOWS- HEADREST SLIP COVER FACTORY OPTION	*CF		118L FO	MTH 19-May-1999		-			
33FO-03 525/J <i>33FO-03 : 525/J</i>	INDIRECT LIGHTING W/DELUXE REFRESHMENT CENTER FACTORY OPTION	*CF		50J FO	MTH 19-May-1999		-			
34FO-03 525/R <i>34FO-03 : 525/R</i>	RADIO ALTIMETER FACTORY OPTION	*CF		672R FO	MTH 19-May-1999		-			
34FO-13	VOICE ANNUNCIATOR FACTORY OPTION	*CF		650 FO	MTH 19-May-1999		-			
35FO-01 525/F <i>35FO-01 : 525/F</i>	OXY-50 CU FT BOTTLE (EXCH) FACTORY OPTION	*CF		66F FO	MTH 19-May-1999		-			
38FO-01 525/C <i>38FO-01 : 525/C</i>	TOILET-FLUSH RH AFT NON-BELT(EXCH) FACTORY OPTION	*CF		130C FO	MTH 19-May-1999		-			
73FO-01 525 <i>73FO-01 : 525</i>	ENGINE SYNCHRONIZER FACTORY OPTION	*CF		76 FO	MTH 19-May-1999		-			